

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008852/KVY3Q2**Date:** 23/03/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00076802201

Claimant Vehicle No : SMY4250H **Insured Vehicle No :** SLN3894B

Date of Loss: 03/09/2022 Nature of Claim: TP Claim No: SNM22D206289/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMY4250H**

Make & Model: HYUNDAI ELANTRA, 1.6 AD GLS (AMS) (A) Engine No: G4FGJU232302

Reg. Date: 21/08/2018 (Man. Year: 2018) Chassis No: KMHD841CMJU725827

Colour: Metallic Light Purple Odometer: 51610 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17

Front Left Side: Goodyear 7 mm Rear Left Side: Goodyear 7 mm

Front Right Side: Goodyear 7 mm Rear Right Side: Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,326.00	1,167.52	8,158.48	87.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	480.00	1,920.00	80.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,726.00	1,647.52	10,078.48	85.95
+ GST 8.00/8.00% (S\$)	938.08	131.80	806.28	85.95
Nett Amount (S\$)	12,664.08	1,779.32	10,884.76	85.95

INSPECTION

Date of Assignment: 08/09/2022

Date Inspected: 09/09/2022 Inspected At:

BH Auto Services Pte Ltd (Sin Ming)
Blk 1 Sin Ming Industrial Estate Sector C,
#01/111/113/115/117
Singapore 575636

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2023)
Parts:	143	HYUNDAI ELANTRA 1.6 AD GLS (AMS) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMY4250H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Cracked	459.40 FL	*459.40 FL
2	1		*REAR BUMPER BLACK DIFFUSAL	Serviceable	250.10 FL	*- FL
3	1		*REAR REINFORCEMENT BAR	Repair	303.70 FL	*- FL
4	1		*BOOT TRUNK	Repair	1,840.00 FL	*- FL
5	1		*REAR FENDER RH	Repair	1,856.60 FL	*- FL
6	1		*REAR BRAKE LIGHT RH	Serviceable	388.00 FL	*- FL
7	1		*REAR BOOT BRAKE LIGHT RH	Serviceable	298.80 FL	*- FL
8	1		*REAR BOOT BRAKE LIGHT LH	Serviceable	298.80 FL	*- FL
9	1		*SPARE TYRE PANEL	Repair	878.30 FL	*- FL
10	1		*ELANTRA EMBLEM	Not Necessary	48.80 FL	*- FL
11	1		*HYUNDAI LOGO EMBLEM	Not Necessary	28.10 FL	*- FL
12	1		*ELITE EMBLEM	Not Necessary	35.00 FL	*- FL
13	1		*REAR REFLECTOR STRIP RH	Serviceable	28.30 FL	*- FL
14	2		*REAR BUMPER RETAINERS	Serviceable	81.60 FL	*- FL
15	1		*BOOT INNER RUBBER SEAL	Serviceable	59.80 FL	*- FL
16	1		*REAR END PANEL	Repair	454.70 FL	*- FL
17	1		*REAR END GARNISH	Serviceable	60.00 FL	*- FL
18	2		*ANTI -RUST COATING	Not Necessary	160.00 FS	*- FS
19	1		*SET REVERSE SENSOR	Serviceable	350.00 FS	*- FS
20	1		*REAR PANEL SEALANT	Not Necessary	150.00 FS	*- FS
21	1		*SET REVERSE CAMERA	Serviceable	350.00 FS	*- FS
22	1		*REAR NUMBER PLATE WITH HOLDER	Serviceable	120.00 FS	*- FS
23	1		*BODY WRAPS	Necessary	1,500.00 FS	*250.00 FS
24	1		*BODY KIT RER DIFFUSAL	Dented / Distorted	800.00 FS	*550.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,800.00	1,259.40
- List Item Discount on L Items 20.00/20.00% (\$)	1,474.00	91.88
Total Parts (\$)	9,326.00	1,167.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS ,PANEL BEAT ,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS (FRONT)	New	1,000.00	200.00
2	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES	New	1,000.00	220.00
3	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING	New	100.00	10.00
4	REMOVE AND REPLACEMENT OF BUMPER SENSOR	New	100.00	50.00
5	REMOVE AND REINSTALL INNER TRAIM GARNISH TO FACILITE REPAIR	New	200.00	0.00
Gross Labour Cost (\$\$)			2,400.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >