

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008855/GNY3Q2**Date:** 10/01/2023REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNA00011842204

Claimant Vehicle No : GBC3306J **Insured Vehicle No :** CB8071X

Date of Loss: 22/08/2022 Nature of Claim: TP Claim No: SNM22D205917/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBC3306J**

Make & Model: NISSAN NV200, 1.5 D MT ABS AIRBAG 2WD 6DR (A) Engine No: K9KF276D124245

Reg. Date: 23/12/2011 (Man. Year: 2011) Chassis No: VSKYBAM20U0026101

Colour: White Odometer: 309924 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14

Front Left Side: Giti 6 mm Rear Left Side: Giti 6 mm

Front Right Side: Giti 6 mm Rear Right Side: Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	1,102.86	846.90	255.96	23.21	
Miscellaneous Items	0.00	0.00	0.00		
Labour	825.00	400.00	425.00	51.52	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	1,927.86	1,246.90	680.96	35.32	
Approved Total (Overridden) (S\$)		1,000.00			
	(S\$)	1,927.86	1,000.00	927.86	48.13
+ GST 7.00/7.00% (S\$)	134.95	70.00	64.95	48.13	
Nett Amount (S\$)	2,062.81	1,070.00	992.81	48.13	

INSPECTION

Date of Assignment: 08/09/2022

Date Inspected: 08/09/2022 Inspected At: ETHOZ Protect Pte Ltd (Tampines)
22 Tampines St 92
Singapore 528876

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 Jan 2023)	
Parts:	N/A	NISSAN NV200 1.5 D MT ABS AIRBAG 2WD 6DR (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC3306J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	670.60 FN	*542.00 FN
2	1		*LH FRONT BUMPER LH RETAINER	Not Necessary	38.20 FN	*- FN
3	10		*BUMPER CLIPS	Necessary	45.00 FN	*30.00 FN
4	1		*LH HEADLAMP LOWER GARNISH	Deformed	471.60 FN	*369.00 FN

F=Franchise part. N=NettItemDisc.

Sub Total (S\$)	1,225.40	941.00
- Nett Item Discount on N Items 10.00/10.00% (S\$)	122.54	94.10
Total Parts (S\$)	1,102.86	846.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	400.00	200.00
2	TO SPRAY PAINT ON AFFECTED PORTIONS	New	400.00	200.00
3	TO CHECK AND RECONNECT NECESSARY WIRINGS	New	25.00	0.00
			Gross Labour Cost (S\$)	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >