

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN	ICE BHD	Ref:	CS3/LPC22008858/Rcy3m4	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date:	26/09/2022	
			Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	YP 6319L	Veh. Inspected	GBJ 2613S	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	22/22/VC05/026261	Excess (\$)	0.00	
	Assign From	GERALD POH	Assign Date	08/09/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA DYNA 150 5MT	c.c	2982	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	JTFAT35Y10K212414	Colour	GREY	
	Odometer	144492 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/70 R15C	YOKOHAMA	7 mm	
	L/H Front Tyre	195/70 R15C	YOKOHAMA	7 mm	
	R/H Rear Tyre	155 R12C (D/D)	YOKOHAMA	5/5 mm	
	L/H Rear Tyre	155 R12C (D/D)	YOKOHAMA	5/5 mm	
4.	I. Description of Damages				
	THE VEHICLE SUS PORTION.	E VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT & REAR O/S RTION.			
5.	5. General Information				
	Accident Date	05/09/2022	Inspect Date / Time	09/09/2022 ( 03:39 PM )	
	Survey held at	MING HUA AUTO SERVICES			
		160 SIN MING DRIVE #02-16 SIN MING AUTO CITY SINGAPORE 575722			
5a.	5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC22008858/Rcy3m4

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser