



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 17 UBI ROAD 4
 SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No. S1000007 / ICLPI1		Customer Details																		
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia			Document No. 0		Mr Chow Weng Fatt 54 Jalan Riang Serangoon Park Singapore 359019 Mobile: 96478122																		
			Document Date 15/09/2022																				
			<table border="1"> <thead> <tr> <th>Year</th> <th>Model</th> <th>Variant</th> <th>Reg. Date</th> <th>Reg. No.</th> <th>Kilometers</th> <th>Wip No.</th> <th>Order No. / Remarks</th> </tr> </thead> <tbody> <tr> <td>2021</td> <td>AXUH80R</td> <td>ANXGB 1P</td> <td>25/08/2021</td> <td>SFD8688X</td> <td>0</td> <td>22035</td> <td>69DS/SFD8688X</td> </tr> </tbody> </table>								Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	2021	AXUH80R	ANXGB 1P	25/08/2021	SFD8688X
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks																
2021	AXUH80R	ANXGB 1P	25/08/2021	SFD8688X	0	22035	69DS/SFD8688X																
Chassis No.		Engine No.		Terms		SA / Counter																	
JTEAD3BH90J000758		A25A0943780		60		Raymond Seah L M																	
Vehicle In		Collected On																					
12/09/2022		9.30		15/09/2022 18.00																			
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount														
1	Z	BP-SUNDRY-AI SUNDRIES TP VEH:YN7644B ACC DATE:07/09/2022 TP INS:LONPAC NO OF REPAIR DAYS:05 DATE-IN:12/09/2022 DATE SURVEY:12/09/2022 BY:LKK-TAUFIK AUTHORISED ON: -TP/DS CLAIM							30.00														
2	B	BP-ECU2 TO RESET ECU AND REPROGRAMME							180.00														
3	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO FOCUS HEADLAMP.							122.40														
4	B	BP-LAB2 TO REPLACE/REPAIR FRONT LH SIDE ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.							1440.00														
5	B	BP-RES2 TO SPRAY PAINT ON FRONT LH SIDE ACCIDENT AFFECTED AREAS.				*			1770.00														
6	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION							274.77														
7	1	T52119-4D977 COVER, FR BUMPER				1.00	676.60		676.60														
8	2	T90467-05170 CLIP				2.00	2.80		5.60														
9	3	T53802-48160 FENDER SUB-ASSY, FR				1.00	1360.60		1360.60														
10	4	T75362-48080 PLATE, FR FENDER				1.00	59.10		59.10														
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 5,919.07																
			Please acknowledge receipt of vehicle		Parts		2,101.90		GST 7.00%	414.33													
					Labour		3,542.40																
					Sublet		274.77		Less		0.00												
					Lubrication/Fluid		0.00																
					Others		0.00		Amount Due		6,333.40												

Company Copy

Vehicle Diagnostic Report

A25A-FXS
013304 km

JTEAD3BH90J000758

Borneo Motors

Printed By: Default User(1)

16/9/2022 2:21:09 pr

Health Check Results All Systems(1 of 2)

Enhanced

System	DTC Related Information						RoB	Calibration	Configure
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed			
Lane Control	Yes	U023587	X				Icon	-	No
Combination Meter	Yes	U018287	X					838004D7 2114	No
								838004D7 2204	
								838004D7 2304	
Pre-Collision System	Yes	U023587	X				Icon	-	No
Front Recognition Camera (Front Lighting Control)	Yes	U018287	X				Icon	-	No
	Yes	U023587	X						
Clearance Warning	Yes	C1AE187	X				Icon	8934F483 5030	No
	Yes	C1AE287	X						
	Yes	C1AE387	X						
	Yes	C1AE487	X						
Entry&Start	No	B27A213	X			X	Icon	02111004 0001	No
Main Body	Yes	U024187	X				Icon	8922F480 8003	No
Blind Spot Monitor "B"	Yes	C1AB413	X				Icon	8816F480 5001	No
Headlight Control (Sub)	Yes	U024187	X					8994G48 04002	No
Hybrid Control							Icon	89983484 9100	No
								89985480 3000	
HV Battery							Icon	8989F480 1000	No
								8989G48 01000	
EMPS							Icon	8965F480 2000	No
								8A311480 2000	
Front Recognition Camera							Icon	8646F481 1100	No
								8646G42 02000	
Brake/EPB							Icon	F152648B 0100	No
Tire Pressure Monitor							Icon	897BF012 1100	No
Front Radar Sensor							Icon	8821F330 1400	No
SRS Airbag							Icon	8917F487 1200	No
Power Source Control							Icon	01211102 0001	No
Blind Spot Monitor "A"							Icon	8816F480 5002	No
Headlight Control							Icon	8994F481 0004	No
Engine								896634D0 7000	No
Motor Generator								89884484 2200	No

Health Check Results

All Systems(2 of 2)

									898844841200	
Radar Cruise1								-	-	No
Radar Cruise2								-	-	No
Rear Camera								-	867B0CB011	No
Steering Angle Sensor								-	8924G4801200	No
Brake Booster								-	F152A4804000	No
D-Door Motor								-	-	No
P-Door Motor								-	-	No
RR-Door Motor								-	-	No
RL-Door Motor								-	-	No
Master Switch								-	-	No
Back Door								-	-	No
Driver Seat								-	8922G4812001	No
Rain and/or Humidity Sensor								-	8971F4805001	No
Navigation System								-	-	No
Tilt&Telescopic								-	-	No
Head Up Display								-	8922J4802100	No
								-	831084808101	No
								-	831084808201	
								-	831084808301	
Central Gateway								-	8911F4804001	No
Air Conditioner								-	8865F4820101	No
Acoustic Vehicle Alerting System								-	8657F4802001	No
Power Distribution Box								-	8273F480300A	No

Tire Pressure / Threshold Value [kPa(abs)]

Sensor 1:345.83 / 290.79
 Sensor 2:345.83 / 294.23
 Sensor 3:349.27 / 294.23
 Sensor 4:344.11 / 294.23
 Sensor 5:N/A / N/A

Vehicle Diagnostic Report

A25A-FXS

013304 km

JTEAD3BH90J000758

Borneo Motors

Printed By: Default User(1)

16/9/2022 2:27:35 pm

Health Check Results

All Systems(1 of 2)

Enhanced

System	DTC Related Information							RoB	Calibration	Configure
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed				
Brake/EPB								Icon	F152648B0100	No
Entry&Start								Icon	021110040001	No
Main Body								Icon	8922F4808003	No
Engine									896634D07000	No
Motor Generator									898844842200	No
									898844841200	
Hybrid Control									899834849100	No
									899854803000	
HV Battery									8989F4801000	No
									8989G4801000	
Radar Cruise1									-	No
Radar Cruise2									-	No
Rear Camera									867B0CB011	No
EMPS									8965F4802000	No
									8A3114802000	
Lane Control									-	No
Front Recognition Camera									8646F4811100	No
									8646G4202000	
Steering Angle Sensor									8924G4801200	No
Tire Pressure Monitor									897BF0121100	No
Brake Booster									F152A4804000	No
D-Door Motor									-	No
P-Door Motor									-	No
RR-Door Motor									-	No
RL-Door Motor									-	No
Master Switch									-	No
Back Door									-	No
									8922G4812001	No
Driver Seat									8971F4805001	No
Rain and/or Humidity Sensor									-	No
Navigation System									-	No
Tilt&Telescopic									8922J4802100	No
Head Up Display									831084808101	No
									831084808201	
									831084808301	

Health Check Results

All Systems(2 of 2)

Combination Meter									838004D7 2114	No
									838004D7 2204	
									838004D7 2304	
Front Radar Sensor									8821F330 1400	No
Pre-Collision System									-	No
Front Recognition Camera (Front Lighting Control)									-	No
Clearance Warning									8934F483 5030	No
Central Gateway									8911F480 4001	No
SRS Airbag									8917F487 1200	No
Air Conditioner									8865F482 0101	No
Power Source Control									01211102 0001	No
Acoustic Vehicle Alerting System									8657F480 2001	No
Blind Spot Monitor "B"									8816F480 5001	No
Blind Spot Monitor "A"									8816F480 5002	No
Headlight Control									8994F481 0004	No
Headlight Control (Sub)									8994G48 04002	No
Power Distribution Box									8273F480 300A	No

Tire Pressure / Threshold Value [kPa(abs)]

Sensor 1:345.83 / 290.79
 Sensor 2:345.83 / 294.23
 Sensor 3:349.27 / 294.23
 Sensor 4:344.11 / 294.23
 Sensor 5:N/A / N/A