

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897**Our File No:** CS/AIS22008871/GQY3Q2**Date:** 18/01/2023**REFERENCE**

Insured/Claimant:	SRIKANTH KRISHNAN	Policy No:	SP2000593621
Date of Loss:	07/09/2022	Nature of Claim:	OD
		Claim No:	202222006576SL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SKX3826H</b>	Engine No:	L15B4027418
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11107414
Reg. Date:	09/12/2015 (Man. Year: 2015)	Odometer:	0 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$50,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,218.30	8,979.80	1,238.50	12.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,170.00	2,450.00	720.00	22.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,388.30</b>	<b>11,429.80</b>	<b>1,958.50</b>	<b>14.63</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>9,150.00</b>		
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	12,788.30	8,550.00	4,238.30	33.14
<b>+ GST 7.00/7.00% (S\$)</b>	895.18	598.50	296.68	33.14
<b>Nett Amount (S\$)</b>	<b>13,683.48</b>	<b>9,148.50</b>	<b>4,534.98</b>	<b>33.14</b>

**INSPECTION**

Date of Assignment:	08/09/2022	Present Location:	Falcon-Air Auto Services Pte Ltd (Tampines)
Date Inspected:	09/09/2022	Inspected At:	Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore
Estimated Period of Repair:	7.0 days		

**Adjuster:** XING GUO QIANG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 18 Jan 2023)
<b>Parts:</b> M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SKX3826H)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Cracked	190.00 F	*190.00 F
2	2		*FRONT BUMPER SIDE RETAINER (WCP)	Cut	26.00 F	*26.00 F
3	1		*FRONT BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
4	1		*FRONT BUMPER LOWER GRILLE (WCP)	Not Necessary	65.00 F	*- F
5	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	250.00 F	*250.00 F
6	2		*FRONT BUMPER REINFORCEMENT MOULDING (WCP)	Cut	50.00 F	*50.00 F
7	1		*FRONT BUMPER LOWER GARNISH (WCP)	Not Necessary	160.00 F	*- F
8	1		*RADIATOR GRILLE BASE (WCP)	Cracked	260.00 F	*260.00 F
9	1		*RADIATOR GRILLE OUTER (WCP)	Cut	175.00 F	*175.00 F
10	2		*RADIATOR GRILLE CHROME (WCP)	Cut	60.00 F	*60.00 F
11	2		*RADIATOR GRILLE SIDE BRACKET (WCP)	Broken	36.00 F	*36.00 F
12	1		*RADIATOR GRILLE LOGO (WCP)	Necessary	18.00 F	*18.00 F
13	1		*RADIATOR GRILLE CENTER BRACKET (WCP)	Broken	28.00 F	*28.00 F
14	1		*FRONT NUMBER PLATE	Missing	45.00 FS	*45.00 FS
15	1		*AMBIENT SENSOR (WCP)	Missing	60.00 F	*60.00 F
16	2		*HEADLAMP (WCP)	Cracked	1,960.00 F	*1,960.00 F
17	2		*HEADLAMP LOWER BRACKET (WCP)	Bent	56.00 F	*56.00 F
18	1		*RADIATOR SUPPORT PANEL ASSY (WCP)	Bent	390.00 F	*390.00 F
19	1		*RADIATOR SUPPORT TOP GARNISH (WCP)	Deformed	70.00 F	*70.00 F
20	1		*RADIATOR SUPPORT TOP GARNISH CLIP (WCP)	Necessary	30.00 F	*30.00 F
21	2		*HORN (WCP)	Cut	160.00 F	*160.00 F
22	2		*HORN BRACKET (WCP)	Bent	70.00 F	*70.00 F
23	1		*AIRCON CONDENSOR (WCP)	Bent	700.00 F	*700.00 F
24	1		*AIRCON FAN COWLING (WCP)	Broken	85.00 F	*85.00 F
25	1		*AIRCON FAN BLADE (WCP)	Not Necessary	60.00 F	*- F
26	1		*AIRCON FAN MOTOR (WCP)	Not Necessary	230.00 F	*- F
27	1		*RADIATOR (WCP)	Bent	850.00 F	*850.00 F
28	1		*RADIATOR FAN COWLING (WCP)	Broken	85.00 F	*85.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
29	1		*RADIATOR FAN MOTOR (WCP)	Not Necessary	235.00 F	*- F
30	1		*RADIATOR FAN BLADE (WCP)	Not Necessary	55.00 F	*- F
31	2		*RADIATOR TOP BRACKET (WCP)	Bent	30.00 F	*30.00 F
32	2		*RADIATOR TOP BRACKET BUSH (WCP)	Bent	30.00 F	*30.00 F
33	1		*RADIATOR TOP HOSE (WCP)	Not Necessary	25.00 F	*- F
34	1		*COOLANT	Necessary	50.00 FS	*30.00 FS
35	1		*BONNET (WCP)	Buckled	480.00 F	*480.00 F
36	2		*BONNET HINGE (WCP)	Bent	76.00 F	*76.00 F
37	1		*BONNET LOCK (WCP)	Jammed	80.00 F	*80.00 F
38	1		*BONNET SEAL (WCP)	Twisted	30.00 F	*30.00 F
39	1		*BONNET INSULATOR (WCP)	Crumpled	95.00 F	*95.00 F
40	1		*BONNET INSULATOR CLIP	Necessary	30.00 FS	*30.00 FS
41	1		*WIPER GARNISH (WCP)	Cut	220.00 F	*220.00 F
42	2		*FRONT FENDER (WCP)	Buckled	520.00 F	*520.00 F
43	1		*FRONT FENDER ARCH GARNISH (WCP)	Deformed	55.00 F	*55.00 F
44	2		*FRONT FENDER INNER SHIELD (WCP)	Not Necessary	170.00 F	*- F
45	1		*FRONT FENDER INNER SHIELD CLIP	Necessary	50.00 FS	*25.00 FS
46	1		*INTAKE MANIFOLD (WCP)	Cut	420.00 F	*420.00 F
47	1		*AIR DUCT (WCP)	Cut	55.00 F	*55.00 F
48	1		*AIR DUCT PIPE (WCP)	Cut	65.00 F	*65.00 F
49	1		*AIR CLEANER BOX (WCP)	Broken	160.00 F	*160.00 F
50	1		*RAD SPARE TANK (WCP)	Not Necessary	35.00 F	*- F
51	1		*AIR CLEANER TOP COVER (WCP)	Not Necessary	50.00 F	*- F
<b>Supplementary #1</b>						
52	1		*WIPER WASHER TANK (WCP)	Crumpled	65.00 F	*65.00 F
53	1		*MANIFOLD TUBE (WCP)	Torn	28.00 F	*28.00 F

F=Franchise part. S=SpcNett.

<b>Sub Total (\$\$)</b>	<b>9,308.00</b>	<b>8,178.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	910.30	801.80
<b>Total Parts (\$\$)</b>	<b>10,218.30</b>	<b>8,979.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK LIGHT AND WIRING	New	50.00	30.00
2	TO VAC, REOIL AND REGAS	New	120.00	120.00
3	TO DIAGNOSE AND CLEAR CODE	New	200.00	100.00
4	LABOUR/PANEL BEATING	New	1,200.00	900.00
5	SPRAY PAINTING	New	1,600.00	1,300.00
			<b>Gross Labour Cost (\$)</b>	<b>3,170.00</b>
				<b>2,450.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >