

# REPAIR DETAILS

## Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 07 Sep 2022)  
**Parts:** M1-SUV      HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** Falcon-Air Auto Services Pte Ltd/SKX3826H/07/09/2022 16:36

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER / CAA	0.00	0.00	*190.00 F
2	2		*FRONT BUMPER SIDE RETAINER / cut	0.00	0.00	*26.00 F
3	1		*FRONT BUMPER CLIP / MBL	0	0.00	*30.00 FS
4	1		*FRONT BUMPER LOWER GRILLE ?	0.00	0.00	*65.00 F
5	1		*FRONT BUMPER REINFORCEMENT / BT	0.00	0.00	*250.00 F
6	2		*FRONT BUMPER REINFORCEMENT MOULDING / cut	0.00	0.00	*50.00 F
7	1		*FRONT BUMPER LOWER GARNISH ?	0.00	0.00	*160.00 F
8	1		*RADIATOR GRILLE BASE / CAA	0.00	0.00	*260.00 F
9	1		*RADIATOR GRILLE OUTER / cut	0.00	0.00	*175.00 F
10	2		*RADIATOR GRILLE CHROME / CA	0.00	0.00	*60.00 F
11	2		*RADIATOR GRILLE SIDE BRACKET / BR	0.00	0.00	*36.00 F
12	1		*RADIATOR GRILLE LOGO / MBL	0.00	0.00	*18.00 F
13	1		*RADIATOR GRILLE CENTER BRACKET / BR	0.00	0.00	*28.00 F
14	1		*FRONT NUMBER PLATE / mis	0	0.00	*45.00 FS
15	1		*AMBIENT SENSOR ?	0.00	0.00	*60.00 F
16	2		*HEADLAMP / CAA	0.00	0.00	*1,960.00 F
17	2		*HEADLAMP LOWER BRACKET / BT	0.00	0.00	*56.00 F
18	1		*RADIATOR SUPPORT PANEL ASSY / BT	0.00	0.00	*390.00 F
19	1		*RADIATOR SUPPORT TOP GARNISH / BL	0.00	0.00	*70.00 F
20	1		*RADIATOR SUPPORT TOP GARNISH CLIP / MBL	0.00	0.00	*30.00 F
21	2		*HORN / cut	0.00	0.00	*160.00 F
22	2		*HORN BRACKET / BT	0.00	0.00	*70.00 F
23	1		*AIRCON CONDENSOR / BT	0.00	0.00	*700.00 F
24	1		*AIRCON FAN COWLING ?	0.00	0.00	*85.00 F
25	1		*AIRCON FAN BLADE ?	0.00	0.00	*60.00 F
26	1		*AIRCON FAN MOTOR ?	0.00	0.00	*230.00 F
27	1		*RADIATOR / BT	0.00	0.00	*850.00 F
28	1		*RADIATOR FAN COWLING ?	0.00	0.00	*85.00 F
29	1		*RADIATOR FAN MOTOR ?	0.00	0.00	*235.00 F
30	1		*RADIATOR FAN BLADE ?	0.00	0.00	*55.00 F
31	2		*RADIATOR TOP BRACKET / BT	0.00	0.00	*30.00 F
32	2		*RADIATOR TOP BRACKET BUSH / BT	0.00	0.00	*30.00 F
33	1		*RADIATOR TOP HOSE ?	0.00	0.00	*25.00 F
34	1		*COOLANT / MBL	0	0.00	*50.00 FS
35	1		*BONNET / Bnc	0.00	0.00	*480.00 F
36	2		*BONNET HINGE / BT	0.00	0.00	*76.00 F
37	1		*BONNET LOCK / Im	0.00	0.00	*80.00 F
38	1		*BONNET SEAL / Bnc	0.00	0.00	*30.00 F
39	1		*BONNET INSULATOR / Comp	0.00	0.00	*95.00 F
40	1		*BONNET INSULATOR CLIP / MBL	0	0.00	*30.00 FS
41	1		*WIPER GARNISH / CA	0.00	0.00	*220.00 F
42	2		*FRONT FENDER / Bnc	0.00	0.00	*520.00 F
43	1		*FRONT FENDER ARCH GARNISH / BL	0.00	0.00	*55.00 F
44	2		*FRONT FENDER INNER SHIELD ?	0.00	0.00	*170.00 F
45	1		*FRONT FENDER INNER SHIELD CLIP / Ad	0	0.00	*50.00 FS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*INTAKE MANIFOLD <i>✓ h.A.</i>	0.00	0.00	*420.00 F
47	1		*AIR DUCT <i>✓ h.A.</i>	0.00	0.00	*55.00 F
48	1		*AIR DUCT PIPE <i>✓ h.A.</i>	0.00	0.00	*65.00 F
49	1		*AIR CLEANER BOX <i>??</i>	0.00	0.00	*160.00 F
50	1		*RAD SPARE TANK <i>??</i>	0.00	0.00	*35.00 F
51	1		*AIR CLEANER TOP COVER <i>??</i>	0.00	0.00	*50.00 F

F=Franchise part. S=SpcNett.

<b>Sub Total (S\$)</b>	<b>9,215.00</b>
<b>+ Margin on L,N Items 10.00% (S\$)</b>	<b>901.00</b>
<b>Total Parts (S\$)</b>	<b>10,116.00</b>

**Falcon-Air Auto Services Pte Ltd/SKX3826H/07/09/2022 16:36.** Not valid without Reference section.  
 Generated using **Merimen e-Claims IEAS**

# Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

# Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	TO CHECK LIGHT AND WIRING	New	30 50.00
2	TO VAC, REOIL AND REGAS	New	1 120.00
3	TO DIAGNOSE AND CLEAR CODE - photo.	New	? 200.00
4	LABOUR/PANEL BEATING	New	900 1,200.00
5	SPRAY PAINTING	New	1300 1,600.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,170.00</b>

Falcon-Air Auto Services Pte Ltd/SKX3826H/07/09/2022 16:36. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

## FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862  
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110  
Website: www.falconair.com.sg Email: email@falconair.com.sg

7 Days. (8)

Lump sum repair

After repair photos.

Not Authorized.

Excess \$600

Gene Qiang - 81880282

9/9/2022.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices on a "no profit" basis
- Third party surveys on a "no prejudice" basis
- No illegal modifications allowed
- Supplementary work is not covered and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: