

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Sep 2022)
Parts: M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Falcon-Air Auto Services Pte Ltd/SKX3826H/07/09/2022 16:36

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

| No. | Qty | Part No. | Particulars | %Disc | %Depr | Amount |
|-----|-----|----------|--------------------------------------------|-------|-----------|------------------|
| 1 | 1 | | *FRONT BUMPER / CAA | 0.00 | 0.00 | *190.00 F ✓ |
| 2 | 2 | | *FRONT BUMPER SIDE RETAINER / cut | 0.00 | 0.00 | *26.00 F ✓ |
| 3 | 1 | | *FRONT BUMPER CLIP / MBL | 0 | 0.00 | nett *30.00 FS ✓ |
| 4 | 1 | | *FRONT BUMPER LOWER GRILLE ? NN | 0.00 | 0.00 | *65.00 F X |
| 5 | 1 | | *FRONT BUMPER REINFORCEMENT / BT | 0.00 | 0.00 | *250.00 F ✓ |
| 6 | 2 | | *FRONT BUMPER REINFORCEMENT MOULDING / cut | 0.00 | 0.00 | *50.00 F ✓ |
| 7 | 1 | | *FRONT BUMPER LOWER GARNISH ? NN | 0.00 | 0.00 | *160.00 F X |
| 8 | 1 | | *RADIATOR GRILLE BASE / CAA | 0.00 | 0.00 | *260.00 F ✓ |
| 9 | 1 | | *RADIATOR GRILLE OUTER / cut | 0.00 | 0.00 | *175.00 F ✓ |
| 10 | 2 | | *RADIATOR GRILLE CHROME / CA | 0.00 | 0.00 | *60.00 F ✓ |
| 11 | 2 | | *RADIATOR GRILLE SIDE BRACKET / BR | 0.00 | 0.00 | *36.00 F ✓ |
| 12 | 1 | | *RADIATOR GRILLE LOGO / MBL | 0.00 | 0.00 | *18.00 F ✓ |
| 13 | 1 | | *RADIATOR GRILLE CENTER BRACKET / BR | 0.00 | 0.00 | *28.00 F ✓ |
| 14 | 1 | | *FRONT NUMBER PLATE / mis | 0 | 0.00 | nett *45.00 FS ✓ |
| 15 | 1 | | *AMBIENT SENSOR ? MIS | 0.00 | 0.00 | *60.00 F ✓ |
| 16 | 2 | | *HEADLAMP / CAA | 0.00 | 0.00 | *1,960.00 F ✓ |
| 17 | 2 | | *HEADLAMP LOWER BRACKET / BT | 0.00 | 0.00 | *56.00 F ✓ |
| 18 | 1 | | *RADIATOR SUPPORT PANEL ASSY / BT | 0.00 | 0.00 | *390.00 F ✓ |
| 19 | 1 | | *RADIATOR SUPPORT TOP GARNISH / re | 0.00 | 0.00 | *70.00 F ✓ |
| 20 | 1 | | *RADIATOR SUPPORT TOP GARNISH CLIP / MBL | 0.00 | 0.00 | *30.00 F ✓ |
| 21 | 2 | | *HORN / cut | 0.00 | 0.00 | *160.00 F ✓ |
| 22 | 2 | | *HORN BRACKET / BT | 0.00 | 0.00 | *70.00 F ✓ |
| 23 | 1 | | *AIRCON CONDENSOR / BT | 0.00 | 0.00 | *700.00 F ✓ |
| 24 | 1 | | *AIRCON FAN COWLING ? BR | 0.00 | 0.00 | *85.00 F ✓ |
| 25 | 1 | | *AIRCON FAN BLADE ? NN | 0.00 | 0.00 | *60.00 F X |
| 26 | 1 | | *AIRCON FAN MOTOR ? NN | 0.00 | 0.00 | *230.00 F X |
| 27 | 1 | | *RADIATOR / BT | 0.00 | 0.00 | *850.00 F ✓ |
| 28 | 1 | | *RADIATOR FAN COWLING ? BR | 0.00 | 0.00 | *85.00 F ✓ |
| 29 | 1 | | *RADIATOR FAN MOTOR ? NN | 0.00 | 0.00 | *235.00 F X |
| 30 | 1 | | *RADIATOR FAN BLADE ? NN | 0.00 | 0.00 | *55.00 F X |
| 31 | 2 | | *RADIATOR TOP BRACKET / BT | 0.00 | 0.00 | *30.00 F ✓ |
| 32 | 2 | | *RADIATOR TOP BRACKET BUSH / BT | 0.00 | 0.00 | *30.00 F ✓ |
| 33 | 1 | | *RADIATOR TOP HOSE ? NN | 0.00 | 0.00 | *25.00 F X |
| 34 | 1 | | *COOLANT / MBL | 0 | nett 0.00 | 30 ✓ *50.00 FS |
| 35 | 1 | | *BONNET / Bue | 0.00 | 0.00 | *480.00 F ✓ |
| 36 | 2 | | *BONNET HINGE / BT | 0.00 | 0.00 | *76.00 F ✓ |
| 37 | 1 | | *BONNET LOCK / Im | 0.00 | 0.00 | *80.00 F ✓ |
| 38 | 1 | | *BONNET SEAL / Bui | 0.00 | 0.00 | *30.00 F ✓ |
| 39 | 1 | | *BONNET INSULATOR / Comp | 0.00 | 0.00 | *95.00 F ✓ |
| 40 | 1 | | *BONNET INSULATOR CLIP / MBL | 0 | 0.00 | nett *30.00 FS ✓ |
| 41 | 1 | | *WIPER GARNISH / CA | 0.00 | 0.00 | *220.00 F ✓ |
| 42 | 2 | | *FRONT FENDER / Bue | 0.00 | 0.00 | *520.00 F ✓ |
| 43 | 1 | | *FRONT FENDER ARCH GARNISH / re | 0.00 | 0.00 | *55.00 F ✓ |
| 44 | 2 | | *FRONT FENDER INNER SHIELD ? NN | 0.00 | 0.00 | *170.00 F X |
| 45 | 1 | | *FRONT FENDER INNER SHIELD CLIP / Ad | 0 | nett 0.00 | 25 ✓ *50.00 FS |

| No. | Qty | Part No. | Particulars | %Disc | %Depr | Amount |
|-----|-----|----------|------------------------------------|-------|-------|-------------|
| 46 | 1 | | *INTAKE MANIFOLD <i>hA.</i> | 0.00 | 0.00 | *420.00 F ✓ |
| 47 | 1 | | *AIR DUCT <i>hA.</i> | 0.00 | 0.00 | *55.00 F ✓ |
| 48 | 1 | | *AIR DUCT PIPE <i>hA.</i> | 0.00 | 0.00 | *65.00 F ✓ |
| 49 | 1 | | *AIR CLEANER BOX <i>?</i> BR | 0.00 | 0.00 | *160.00 F ✓ |
| 50 | 1 | | *RAD SPARE TANK <i>?</i> NN | 0.00 | 0.00 | *35.00 F ✗ |
| 51 | 1 | | *AIR CLEANER TOP COVER <i>?</i> NN | 0.00 | 0.00 | *50.00 F ✗ |

F=Franchise part. S=SpcNett.

7925
+10%
8717.50

nett -160

Sub Total (S\$)
+ Margin on L,N Items 10.00% (S\$)

9,215.00
901.00

Total Parts (S\$)

10,116.00

Falcon-Air Auto Services Pte Ltd/SKX3826H/07/09/2022 16:36. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

| No | Particulars | Lab.Type | Amount |
|---------------------------------|-------------------------------------|-------------|-----------------|
| Labour Items | | | |
| 1 | TO CHECK LIGHT AND WIRING | New | 30 ✓ 50.00 |
| 2 | TO VAC, REOIL AND REGAS | New | ✓ 120.00 |
| 3 | TO DIAGNOSE AND CLEAR CODE - photo. | New | 100 ✓ ? 200.00 |
| 4 | LABOUR/PANEL BEATING | New | ✓ 900 1,200.00 |
| 5 | SPRAY PAINTING | New | ✓ 1300 1,600.00 |
| | | 2450 | |
| Gross Labour Cost (\$\$) | | | 3,170.00 |

Falcon-Air Auto Services Pte Ltd/SKX3826H/07/09/2022 16:36. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

7 Days. (8)

Lump sum repair

After repair photos.

Not Authorized.

Excess \$600

Gene Qiang - 81880282

9/9/2022.

part - 8717.50
nett - 160
labour - 2450
supp - 102.30
11,429.80

L/S - 9143.84
= 9150

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices on a "no profit" basis
- Third party survey on a "no prejudice" basis
- No illegal modification allowed
- Supplementary work is not covered and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Oct 2022)**Parts:** M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Falcon-Air Auto Services Pte Ltd/SKX3826H/13/10/2022 16:26**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

| No. | Qty | Part No. | Particulars | %Disc | %Depr | | Amount |
|-----|-----|----------|--------------------|-------|-------|-----|-------------------------------------------------------|
| 1 | 1 | | *WIPER WASHER TANK | 0.00 | 0.00 | CRU | *65.00 F ✓ |
| 2 | 1 | | *MANIFOLD TUBE | 0.00 | 0.00 | TN | *28.00 F ✓ |
| | | | | | | | F=Franchise part. |
| | | | | | | | Sub Total (S\$) 93.00 |
| | | | | | | | + Margin on L,N Items 10.00% (S\$) 9.30 |
| | | | | | | | Total Parts (S\$) 102.30 ✓ |

Falcon-Air Auto Services Pte Ltd/SKX3826H/13/10/2022 16:26. Not valid without Reference section.
Generated using Merimen e-Claims IEAS