



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 9339P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEEP CUT	1,699.77	1,445.00
1	FRONT BUMPER SIDE RETAINER RH	NOT NECESSARY	188.98	-
10	FRONT BUMPER CLIPS	NECESSARY	70.00	50.00
1	FRONT FENDER RH	WARPED	872.71	872.71
1	SIDE MIRROR	CRACKED	889.31	889.31
1	SIDE MIRROR COVER }	CRACKED	190.71	190.71
1	SIDE MIRROR LOWER GARNISH - OUTER }		130.77	-
1	SIDE MIRROR LOWER GARNISH - INNER }		129.75	-
1	SIDE MIRROR LAMP	SCRATCHED	100.77	100.77
1	FRONT DOOR OUTER HANDLE RH	SCRATCHED	297.77	297.77
	LESS 10% DISCOUNT		-457.05	-384.63
			4,113.49	3,461.64
1	SPORT RIM ASSY FRONT RH (SN)	WARPED	1,400.77	600.00
	LESS 10% DISCOUNT		-140.08	-
			1,260.69	600.00
	<u>LABOUR</u>			
	TO CHECK & ADJUST COMPUTER WHEEL ALIGNMENT.		120.00	80.00
	TO REMOVE & REFIX FRONT RH SPORT RIM & CONTRACT WHEEL BALANCING.	NOT NECESSARY	120.00	-
	TO RESPRAY AFFECTED AREAS.		900.00	850.00
	TO RENEW DAMAGED PARTS, STRAIGHTEN & REPAIR FRONT RH DOOR, REAR RH DOOR AND ALIGNED ALL PARTS.		800.00	400.00
	TO CHECK & RESET ELECTRICAL MOUDLE SYSTEM.	NOT NECESSARY	200.00	-
			2,140.00	1,330.00
	GRAND TOTAL		7,514.18	5,391.64

Report Ref No. CS/GAI22008873/Uvy3m4



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,300.00
---	--	--	-----------------

Report Ref No. CS/GAI22008873/Uvy3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.