



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 7940X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	568.20	486.00
1	FRONT BUMPER GRILLE (LOWER)	NOT NECESSARY	196.20	-
2	FRONT BUMPER O/S & N/S RETAINER	NOT NECESSARY	182.00	-
1	FRONT BUMPER N/S FOG LAMP GARNISH	NOT NECESSARY	88.60	-
1	FRONT GRILLE	CRACKED	286.20	286.20
1	FRONT EMBLEM	NECESSARY	70.40	40.00
	LESS 25% DISCOUNT		-347.90	-203.05
			1,043.70	609.15
<u>SPECIAL NETT ITEMS</u>				
10	FRONT BUMPER CLIPS (SN)	NECESSARY	40.00	40.00
4	FRONT GRILLE CLIPS (SN)	NECESSARY	16.00	16.00
1	FRONT REG. NO. PLATE (SN)	CUT	45.00	30.00
			101.00	86.00
<u>LABOUR</u>				
	TO DISMANTLE FRONT PORTION, STRAIGHTEN & WELDING.		400.00	200.00
	TO SPRAY PAINTING.		400.00	200.00
	TO CHECK WIRING.		120.00	30.00
			920.00	430.00
GRAND TOTAL			2,064.70	1,125.15
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				900.00

Report Ref No. CS/AGI22008874/Avy3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.