

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22008875/AVY3Q2**Date:** 14/06/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00152822101
<b>Claimant Vehicle No :</b>	YP6740C	<b>Insured Vehicle No :</b>	GBG9913X
Date of Loss:	06/09/2022	Nature of Claim:	TP
		Claim No:	SNM22D206391/C02/IRENE

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>YP6740C</b>	Engine No:	4P10C56363
Make & Model:	MITSUBISHI CANTER, 2.5 D FB510B (M)	Chassis No:	FEB71EA20414
Reg. Date:	29/06/2017 (Man. Year: 2016)	Odometer:	229122 km
Colour:	White		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/75 R17.5	Rear Tyre Size:	215/75 R17.5
Front Left Side:	Windforce 6 mm	Rear Left Side:	Windforce 6 mm
Front Right Side:	Windforce 6 mm	Rear Right Side:	Windforce 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	32,762.50	13,262.22	19,500.28	59.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,980.00	2,990.00	2,990.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>38,742.50</b>	<b>16,252.22</b>	<b>22,490.28</b>	<b>58.05</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>13,000.00</b>		
<b>(S\$)</b>	38,742.50	13,000.00	25,742.50	66.45
<b>+ GST 8.00/8.00% (S\$)</b>	3,099.40	1,040.00	2,059.40	66.45
<b>Nett Amount (S\$)</b>	<b>41,841.90</b>	<b>14,040.00</b>	<b>27,801.90</b>	<b>66.45</b>

**INSPECTION**

Date of Assignment:	25/10/2022	
Date Inspected:	09/09/2022 Inspected At:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	10.0 days	

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 14 Jun 2023)	
<b>Parts:</b>	N/A	MITSUBISHI CANTER 2.5 D FB510B (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for YP6740C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CABIM PANEL MECHANISM LOCK	Not Necessary	189.90 FL	*- FL
2	1		*CABIN REAR PANEL	Dented	1,148.40 FL	*1,148.40 FL
3	1		*CABIN PANEL OPENER HANDLE	Not Necessary	276.22 FL	*- FL
4	1		*CABIN REAR PANEL GLASS WEATHERSTRIP	Necessary	195.75 FL	*195.75 FL
5	1		*ENGINE MANIFOLD OUTLET PIPE LINES	Not Necessary	952.00 FL	*- FL
6	1		*ENGINE OUTLET HOSE	Damaged	117.00 FL	*117.00 FL
7	1		*ENGINE OUTLET HOSE CASING	Not Necessary	259.00 FL	*- FL
8	1		*FRONT DOOR END PILLAR L/R	N/S Dented	3,066.48 FL	*950.00 FL
9	1		*FRONT RH AIR CLEANER DUCT	Deformed	365.10 FL	*365.10 FL
10	1		*REAR NUMBER PLATE LAMP	Not Necessary	200.05 FL	*- FL
11	1		*REAR TAILLAMP L/R	N/S Cut	480.10 FL	*240.05 FL
12	8		*FLOOR HORIZONTAL WOODEN PANEL	Cracked (4 PCS ONLY)	4,000.00 FS	*1,600.00 FS
13	2		*FLOOR WOODEN CHASSIS MEMBER L/R	Not Necessary	3,600.00 FS	*- FS
14	1		*FLOOR WOODEN PANEL	Not Necessary	1,200.00 FS	*- FS
15	1		*REAR CABIN FRAME ALUMINIUM PANEL	Bent	600.00 FS	*400.00 FS
16	1		*REAR CABIN FRAME PANEL	Bent	1,200.00 FS	*800.00 FS
17	1		*REAR CANOPY FRAME	Bent	1,800.00 FS	*1,200.00 FS
18	2		*REAR FENDER ARCH GARNISH L/R	Deformed	1,000.00 FS	*800.00 FS
19	1		*REAR NUMBER PLATE	Not Necessary	25.00 FS	*- FS
20	1		*REAR NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
21	1		*REAR NUMBER PLATE PANEL BRACKET	Not Necessary	180.00 FS	*- FS
22	1		*SET REAR REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
23	1		*SET REAR REVERSE SENSOR BRACKET	Damaged	80.00 FS	*50.00 FS
24	1		*REAR STEP BRACKET	Bent	800.00 FS	*400.00 FS
25	1		*REAR TAILGATE	Dented	2,700.00 FS	*1,800.00 FS
26	1		*REAR TAILGATE 22 PAX STICKER	Necessary	25.00 FS	*15.00 FS
27	1		*REAR TAILGATE 60KM/H STICKER	Necessary	25.00 FS	*15.00 FS
28	1		*REAR TAILGATE ALUMINIUM CHECKER PANEL	Not Necessary	800.00 FS	*- FS
29	1		*REAR TAILGATE ALUMINIUM CHECKER PANEL REPAIR KIT	Necessary	150.00 FS	*80.00 FS
30	1		*REAR TAILGATE LOWER PANEL	Repair	1,100.00 FS	*- FS
31	2		*REAR TAILGATE OPENER HANDLE L/R	Damaged	440.00 FS	*440.00 FS
32	1		*REAR UNDER BUMPER	Bent	1,500.00 FS	*1,000.00 FS
33	1		*SIDE GATE PANEL L/R	O/S Dented	5,800.00 FS	*2,200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 34,575.00 14,016.30**  
**- List Item Discount on L Items 25.00/25.00% (\$\$) 1,812.50 754.08**

**Total Parts (\$\$) 32,762.50 13,262.22**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT REAR WINDSCREEN	New	120.00	80.00
2	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	140.00	80.00
3	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	2,000.00	1,200.00
4	TO PROVIDE LABOUE ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENT AND DAMAGED CONSISTENT TO THE ACCIDENT	New	2,400.00	1,100.00
5	TO APPLY ANTI -RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	80.00
6	TO REMOVE N REFIX FLOOR CARRIER DECK INORDER TO REPLACE ABOVE ITEM	New	1,200.00	450.00
<b>Gross Labour Cost (S\$)</b>			<b>5,980.00</b>	<b>2,990.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**