



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 3243M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HEAD LAMP ASSY. LH	SCRATCHED / CUT	3,668.70	3,668.70
2	HEAD LAMP HOLDER @\$128.00	NOT NECESSARY	256.00	-
1	BUMPER	CUT / DISTORTED	1,130.00	1,023.10
2	BUMPER SIDE RETAINER	NECESSARY	198.30	156.20
1	GRILLE CHROME	CRACKED / CUT	698.60	285.00
1	BUMPER LOWER GRILLE	NOT NECESSARY	890.00	-
1	SET BUMPER PARKING SENSOR	SERVICEABLE	398.00	-
1	FENDER GARNISH	CUT	386.80	215.40
1	LH DAY LIGHT	NOT NECESSARY	299.00	-
	LESS 20% DISCOUNT		-	-1,069.68
			7,925.40	4,278.72
<u>SPECIAL NETT ITEMS</u>				
10	BUMPER CLIPS @\$6.00 (SN)	NECESSARY	60.00	20.00
			60.00	20.00
<u>LABOUR</u>				
	TO REMOVE & REFIT WIRINNG CHECK & REFOCUS HEAD LAMP.		200.00	30.00
	TO REPAIR & RENEW ALL ACCIDENT DAMAGED ACCIDENT AFFECTED PARTS.		1,000.00	400.00
	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED AREA.		1,000.00	400.00
			2,200.00	830.00
GRAND TOTAL			10,185.40	5,128.72
RECOMMENDED COST OF REPAIRS				5,128.72

Report Ref No. CS/TP22008879/Dcy3e2

Remark: Left headlamp and front bumper not available in Singapore. Repairer indents from overseas.

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.