



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2303063

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 16/05/2023
Reference CC6/CTI22008881/Apa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMH 525G
Insured Veh. SJD 9067J
Claim No. SNM22D206433/C02
Policy No. DMPCSNW00072692200
Accident Date 07/09/2022
Inspection Date 08/09/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22008881/Apa3q2 Date: 16/05/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJD 9067J	Veh. Inspected	SMH 525G	
Policy No.	DMPCSNW00072692200	Coverage (\$)	0.00	
Claim No.	SNM22D206433/C02	Excess (\$)	0.00	
Assign From		Assign Date	08/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA NOAH HYBRID	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	ZWR800351548	Colour	BLACK	
Odometer	218692 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/09/2022	Inspection Date	08/09/2022	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 525G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	DISTORTED	2,080.50	1,812.00
1	TAILGATE LOGO	NECESSARY	85.00	85.00
1	TAILGATE EMBLEM 'HYBRID SYNERGY DRIVE'	NECESSARY	82.50	82.50
2	TAILGATE HINGE @\$130.00	NOT NECESSARY	260.00	-
2	TAIL GATE DAMPER @\$230.00	NOT NECESSARY	460.00	-
1	TAILGATE LOCK	DAMAGED	480.00	368.00
1	TAILGATE INNER BOARD TRIM	CRACKED	766.20	570.00
1	TAILGATE WEATHERSTRIP	CUT	330.00	330.00
1	TAILGATE INNER HANDLE	CRACKED	90.00	65.00
1	REAR WINDSCREEN MOULDING	NECESSARY	190.00	190.00
1	TAILGATE ALTERNATIVE	CRACKED	210.00	210.00
1	TAILGATE BUZZEL	NOT NECESSARY	150.30	-
1	TAILGATE CENTRE CHROME	NOT NECESSARY	733.50	-
1	REAR BUMPER	DEFORMED	822.30	822.30
2	REAR BUMPER SIDE RETAINER @\$62.40	NECESSARY	124.80	124.80
1	REAR BUMPER TOWING COVER	DEFORMED	98.20	98.20
2	REAR BUMPER REFLECTOR @\$110.20	CRACKED	220.40	220.40
2	REAR BUMPER BRACKET @\$80.00	NOT NECESSARY	160.00	-
2	REAR CORNER BUMPER @\$320.00	DEFORMED	640.00	560.00
2	REAR CORNER BUMPER RETAINER @\$103.20	NOT NECESSARY	206.40	-
2	REAR FENDER INNER TRIM BELOW @\$799.50	O/S CRACKED	1,599.00	799.50
1	REAR END PANEL	DENTED	666.50	666.50
1	REAR END PANEL TOP GARNISH	DEFORMED	211.50	211.50
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	912.30	-
1	REAR FLOOR PANEL TOP BOARD	DEFORMED	820.30	691.00
1	REAR FLOOR PANEL MAT	NOT NECESSARY	680.30	-
1	TOOLS COVER	DEFORMED	144.70	144.70
	LESS 25% DISCOUNT		-3,306.18	-2,012.85
			9,918.52	6,038.55

Report Ref No. CC6/CTI22008881/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET TAILGATE INNER BOARD CLIPS (SN)	NECESSARY	20.00	20.00
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	100.00	60.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	20.00	20.00
1	SET REAR FENDER INNER TRIM CLIPS (SN)	NECESSARY	20.00	20.00
1	SET REAR END PANEL GARNISH CLIP (SN)	NECESSARY	20.00	20.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	150.00	60.00
1	REAR FLOOR PANEL SEALANT (SN)	NOT NECESSARY	150.00	-
1	REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
			750.00	400.00
	<u>LABOUR</u>			
	TO PANEL BEAT ,REMOVE AND REPALCE PARTS .INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL .		2,000.00	800.00
	TO SPRAY PAINT AFFECTED AREA .		2,000.00	800.00
	TUFF COAT.		250.00	60.00
	WIRING CHECK .		120.00	30.00
	TO CONDUCT WATER LEAKAGE TEST .	NOT NECESSARY	100.00	-
	TO TRANSFER TAIL GATE WINDSCREEN .		180.00	60.00
	LABOUR TO REMOVE AND REFIT WINDSCREEN.		120.00	120.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	50.00
	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING.		80.00	50.00
	REMOVE AND REFIX CAR BATTERY .	NOT NECESSARY	100.00	-
	REMOVE AND REFIX EXHAUST PIPE .	NOT NECESSARY	250.00	-
	REMOVE AND REFIX REAR AIRCON BLOWER N TOP UP AIRCON GAS .	NOT NECESSARY	120.00	-
			5,400.00	1,970.00
	GRAND TOTAL		16,068.52	8,408.55

Report Ref No. CC6/CTI22008881/Apa3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,700.00
---	--	--	----------

Report Ref No. CC6/CTI22008881/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMH 525G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMH 525G

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMH 525G

RE-INSPECTION

