

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22008891/GNY3Q2**Date:** 14/12/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCNSA00002032201

**Claimant Vehicle No :** SJP3861J **Insured Vehicle No :** SMP683R

Date of Loss: 08/09/2022 Nature of Claim: TP Claim No: SNM22D206425/C02/TOHHS

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SJP3861J**

Make & Model: HONDA STREAM, 1.8 L (A) Engine No: R18A13800137

Reg. Date: 19/01/2009 (Man. Year: 2008) Chassis No: JHMRN68609S200127

Colour: White Odometer: 239960 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 225/45Z R17 Rear Tyre Size: 225/45Z R17

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

*The above values represent the remaining tyre tread depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 2,951.20          | 2,206.40          | 744.80            | 25.24         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 1,640.00          | 1,120.00          | 520.00            | 31.71         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>4,591.20</b>   | <b>3,326.40</b>   | <b>1,264.80</b>   | <b>27.55</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>2,650.00</b>   |                   |               |
| <b>(S\$)</b>                             | 4,591.20          | 2,650.00          | 1,941.20          | 42.28         |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 321.38            | 185.50            | 135.88            | 42.28         |
| <b>Nett Amount (S\$)</b>                 | <b>4,912.58</b>   | <b>2,835.50</b>   | <b>2,077.08</b>   | <b>42.28</b>  |

**INSPECTION**

Date of Assignment: 09/09/2022

Date Inspected: 09/09/2022 Inspected At: Vin's Auto Pte Ltd (Vin's Auto)  
Sin Ming AutoCity, 160 Sin Ming Drive #03-03  
Singapore 575722

Estimated Period of Repair: 4.0 days

**Adjuster:** XING GUO QIANG**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|  |  |
|--|--|
| <b>Part Source:</b> MRM-SG                                   | Version: 1.0 (Last Synchronised: 14 Dec 2022)  |
| <b>Parts:</b> M1-MPV   | HONDA STREAM 1.8 L (A) (Catalogue:Merimen Singapore 1.0)   |
| <b>Labour:</b> Repairer's                                    | (Price-denominated Standard List)  |
| <b>Print Code:</b> (Unsubmitted, no print-code for SJP3861J) |  |
| <b>Validity:</b>   | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>   | Items/values not in reference catalogue are prefixed with an asterisk *.   |

### Recommended Parts

| No. | Qty | Part No. | Particulars                 | Condition     | Repairer's | Amount     |
|-----|-----|----------|-----------------------------|---------------|------------|------------|
| 1   | 1   |          | *REAR BOOT                  | Buckled       | 991.80 FL  | *991.80 FL |
| 2   | 1   |          | *REAR BOOT HONDA LOGO       | Not Necessary | 22.50 FL   | *- FL      |
| 3   | 1   |          | *REAR BOOT STREAM LOGO      | Necessary     | 41.70 FL   | *41.70 FL  |
| 4   | 1   |          | *REAR BOOT PLASTIC GARNISH  | Not Necessary | 223.80 FL  | *- FL      |
| 5   | 1   |          | *REAR BOOT INNER TRIM BOARD | Broken        | 175.30 FL  | *175.30 FL |
| 6   | 1   |          | *REAR BOOT RUBBER           | Cut           | 133.90 FL  | *133.90 FL |
| 7   | 1   |          | *REAR BOOT LOCK             | Cut           | 154.80 FL  | *154.80 FL |
| 8   | 1   |          | *REAR BUMPER                | Deformed      | 674.80 FL  | *674.80 FL |
| 9   | 1   |          | *REAR BUMPER TOW COVER      | Not Necessary | 13.50 FL   | *- FL      |
| 10  | 10  |          | *REAR BUMPER CLIPS          | Necessary     | 42.00 FL   | *42.00 FL  |
| 11  | 1   |          | *REAR END PANEL             | Repair        | 346.20 FL  | *- FL      |
| 12  | 1   |          | *REAR END PANEL GARNISH     | Deformed      | 176.90 FL  | *176.90 FL |
| 13  | 1   |          | *REAR WINDSCREEN MOULDING   | Necessary     | 66.80 FL   | *66.80 FL  |
| 14  | 1   |          | *REAR NUMBER PLATE W HOLDER | Not Necessary | 40.00 FS   | *- FS      |
| 15  | 1   |          | *REAR BUMPER REVERSE SENSOR | Damaged       | 380.00 FS  | *200.00 FS |
| 16  | 1   |          | *WINDSCREEN GUM             | Necessary     | 80.00 FS   | *40.00 FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|  |                 |                 |
|--|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>3,564.00</b> | <b>2,698.00</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b> | 612.80          | 491.60          |
| <b>Total Parts (\$\$)</b>                                  | <b>2,951.20</b> | <b>2,206.40</b> |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                             | Particulars                      | Lab.Type | Repairer's      | Amount          |
|--------------------------------|----------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                  |          |                 |                 |
| 1                              | REMOVE AND REFIX REAR WINDSCREEN | New      | 180.00          | 120.00          |
| 2                              | TO REPAIR DAMAGES                | New      | 680.00          | 400.00          |
| 3                              | TO SPRAY PAINTING                | New      | 780.00          | 600.00          |
| <b>Gross Labour Cost (S\$)</b> |                                  |          | <b>1,640.00</b> | <b>1,120.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >