

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22008892/UPA3Q2**Date:** 20/03/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP0001073670
Claimant Vehicle No :	SMD560A	Insured Vehicle No :	SMQ9014H
Date of Loss:	04/09/2022	Nature of Claim:	TP
		Claim No:	202222006604

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD560A	Engine No:	10XVA10930682
Make & Model:	CITROEN C4 CACTUS, 1.2 AT6 (A)	Chassis No:	VF70PHNZWJE504483
Reg. Date:	31/07/2018 (Man. Year: 2018)	Odometer:	49778 km
Colour:	Purple		
Engine Capacity:	1199 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,883.00	4,509.00	6,374.00	58.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,210.00	770.00	1,440.00	65.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,093.00	5,279.00	7,814.00	59.68
Approved Total (Overridden) (\$\$)		4,280.00		
Nett Amount (\$\$)	13,093.00	4,280.00	8,813.00	67.31
+ Car Rental (4.0 x S\$100.00/day) (\$\$)		400.00		
Nett Liability (\$\$)		4,680.00		

INSPECTION

Date of Assignment:	09/09/2022	
Date Inspected:	13/09/2022	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 20 Mar 2023)	
Parts:	N/A	CITROEN C4 CACTUS 1.2 AT6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD560A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Torn	1,650.00 F	*1,128.00 FL
2	1		*FRONT BUMPER LOWER PAD	Deformed / Torn	1,450.00 F	*680.00 FL
3	1		*FRONT BUMPER LICENCE PLATE GARNISH	Cut	620.00 F	*202.00 FL
4	1		*FRONT BUMPER INNER TOP RETAINER	Cracked	455.00 F	*244.00 FL
5	1		*FRONT BUMPER INNER RETAINER	Cracked	588.00 F	*280.00 FL
6	1		*FRONT BUMPER BEAM	Bent	885.00 F	*615.00 FL
7	1		*FRONT SIGNAL LAMP N/S	Cracked	680.00 F	*395.00 FL
8	1		*FRONT HEADLAMP N/S	Cracked	1,280.00 F	*920.00 FL
9	1		*FRONT HEADLAMP OUTER PAD N/S	Torn	450.00 F	*180.00 FL
10	1		*FRONT SUPPORT PANEL	Not Necessary	800.00 F	*- FL
11	1		*FRONT FENDER N/S	Repair	565.00 F	*- FL
12	1		*FRONT FENDER OUTER PROTECTOR N/S	Deformed / Torn	380.00 F	*266.00 FL
13	1		*CONDENSER	Not Necessary	980.00 F	*- FL
14	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
15	1		*FRONT LICENCE PLATE	Scratched	50.00 FS	*40.00 FS
					Sub Total (S\$)	
					10,883.00	5,000.00
					- List Item Discount on L Items 0.00/10.00% (S\$)	
					0.00	491.00
					Total Parts (S\$)	
					10,883.00	4,509.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO REFILL AIR CON GAS	New	120.00	0.00
3	TO SPRAY RUST PROOFING	New	60.00	0.00
4	TO DIAGNISTIC SYSTEM	New	100.00	0.00
5	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	800.00	450.00
6	TO PUTTY & SPRAY PAINTING	New	1,080.00	300.00
Gross Labour Cost (S\$)			2,210.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >