

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22008894/UVY3Q2
Date: 03/04/2023**REFERENCE**

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SMT2178Z	Insured Vehicle No :	SKN983J
Date of Loss:	08/09/2022	Nature of Claim:	TP
		Claim No:	DMPC2200404H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT2178Z	Engine No:	37065896B38A15A
Make & Model:	ADIVA AD1 200, 190cc 3W	Chassis No:	WBA6V120505P83430
Reg. Date:	31/03/2020 (Man. Year: 2019)	Odometer:	59624 km
Colour:	Pearl White		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,559.00	4,697.00	4,862.00	50.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,350.00	1,410.00	940.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,909.00	6,107.00	5,802.00	48.72
+ GST 8.00/8.00% (S\$)	952.72	488.56	464.16	48.72
Nett Amount (S\$)	12,861.72	6,595.56	6,266.16	48.72

INSPECTION

Date of Assignment:	09/09/2022		
Date Inspected:	23/09/2022	Inspected At:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 03 Apr 2023)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT2178Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Cut	800.00 F	*800.00 F
2	2		*FRONT BUMPER SIDE HOLDER -LH/RH (TOP) (WCP)	Not Necessary	50.00 F	*- F
3	2		*FRONT BUMPER SIDE HOLDER -LH/RH (LOWER) (WCP)	Not Necessary	40.00 F	*- F
4	10		*FRONT BUMPER CLIPS (WCP)	Necessary	20.00 F	*20.00 F
5	1		*FRONT BUMPER SENSOR -RH (WCP)	Not Necessary	290.00 F	*- F
6	1		*FRONT FENDER -RH (WCP)	Dented / Bent	750.00 F	*750.00 F
7	1		*FRONT FENDER COWLING -RH (WCP)	Not Necessary	160.00 F	*- F
8	10		*FRONT FENDER COWLING CLIPS -RH (WCP)	Not Necessary	15.00 F	*- F
9	1		*FRONT FENDER M SPORT LOGO (WCP)	Scratched	100.00 F	*100.00 F
10	1		*FRONT DOOR-RH (WCP)	Repair	900.00 F	*- F
11	1		*FRONT DOOR STICKER -RH (WCP)	Not Necessary	50.00 F	*- F
12	1		*FRONT DOOR LOWER RUBBER -RH (WCP)	Not Necessary	30.00 F	*- F
13	1		*SIDE MIRROR HOUSING -RH (WCP)	Cracked	650.00 F	*650.00 F
14	1		*SIDE MIRROR GLASS-RH (WCP)	Serviceable	760.00 F	*- F
15	1		*SIDE MIRROR GLASS OUTER BLACK FRAME -RH (WCP)	Cracked	90.00 F	*90.00 F
16	1		*SIDE MIRROR LAMP -RH (WCP)	Cracked	55.00 F	*55.00 F
17	1		*SIDE MIRROR MOTOR -RH (WCP)	Serviceable	560.00 F	*- F
18	1		*SIDE MIRROR OUTER COVER (UPPER)-RH (WCP)	Cracked	80.00 F	*80.00 F
19	1		*SIDE MIRROR OUTER COVER (LOWER)-RH (WCP)	Cracked	65.00 F	*65.00 F
20	1		*FRONT RIM -RH (WCP)	Warped	1,550.00 F	*1,550.00 F
21	1		*FRONT RIM BMW HUB CAP -RH (WCP)	Not Necessary	20.00 F	*- F
22	1		*FRONT LOWER ARM BRACKET -RH (WCP)	Not Necessary	125.00 F	*- F
23	1		*FRONT KNUCKLE -RH (WCP)	Not Necessary	450.00 F	*- F
24	1		*FRONT KNUCKLE BEARING-RH (WCP)	Not Necessary	300.00 F	*- F
25	1		*FRONT ABSORBER -RH (WCP)	Not Necessary	230.00 F	*- F
26	1		*FRONT ABSORBER TOP MOUNTING -RH	Not Necessary	150.00 F	*- F
27	1		*FRONT LOWER ARM -RH (WCP)	Not Necessary	290.00 F	*- F
28	1		*FRONT FOG LAMP COVER -RH (WCP)	Cracked	75.00 F	*75.00 F
29	1		*FRONT FOG LAMP COVER -RH (SMALL) (WCP)	Cracked	35.00 F	*35.00 F

F=Franchise part.

Sub Total (\$)	8,690.00	4,270.00
+ Margin on L,N Items 10.00/10.00% (\$)	869.00	427.00
Total Parts (\$)	9,559.00	4,697.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS ,REMOVE ,REPLACE ACCIDENT PARTS	New	600.00	500.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,125.00	800.00
3	TO CHECK WIRING	New	40.00	20.00
4	TO TRANSFER DOOR & DOOR FITTINGS	New	80.00	0.00
5	TO 4 WHEEL ALIGNMENT	New	80.00	60.00
6	TO REMOVE ,REPLACE FRONT RH UNDERCARRIAGE	New	300.00	0.00
7	TO REMOVE ,REPLACE RIM & TYRE BALANCING	New	45.00	0.00
8	TO TUFF-KOTE	New	80.00	30.00
Gross Labour Cost (S\$)			2,350.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >