

SGX66J8R. 2014 NOV.

Mercedes Benz. E200

TPAXA
Veron.

WDD2130422A069556.

Rees Number Plate.	Best	30(SN)	✓
Rees Number Plate Holder	Dehd	30(SN)	✓
Rees Number Plate Lamp x 02	not in Dehd	75x2 = 150	+
Rees Number Plate Lamp Garnish.		68	✓
Rees Bumper	Dehd	1874	✓
Rees Bumper Clips.	not in	50(SN)	✓
Rees Bumper Side Holder x 02	not in	192x2 = 384	+
Rees Bumper Reflector x 02	not in	69x2 = 138	+
Rees Bumper Tow Cover	not in	59	+
Rees Bumper Reinforcement	Dented	846	✓
Rees Bumper Centre Guide.	Dehd	275	✓
Rees Bumper Lower Garnish.	not in	485	✓
Rees Bumper Lower Garnish Chrome Moulding.	not in	291	✓
Rees Bumper Lower Garnish Exhaust Chrome x 02	not in	231x2 = 462	✓
		231	

SGX6628R.

Reese Bumper Lower Kick Sensor	NH neu	316 +
Reverse Sensor x 04.	2 pieces damaged	$268 \times 4 = 1072$ ⁵³⁶
Reverse Sensor Holder x 04	neu	$25 \times 4 = 100$ ✓
Reverse Sensor Wire Harness.	NH neu	622 X.
Reese End Panel	Dented	1302 ✓
Reese End Panel Top Garnish	Deformed	229 ✓
Reese End Panel Top Garnish Caps.	neu	20(SN) ✓
Reese End Panel Sealant.	neu	60(SN) ✓
Taillamp x 02	Cracked	$785 \times 2 = 1570$ ✓
Taillamp Lower Bracket x 02	NH cracked	$67 \times 2 = 134$ ⁶⁷
Taillamp Panel x 02	Reps	$292 \times 2 = 584$ X
Bootlid	Dented	2399 ✓
Bootlid Lock	2	294 ✓
Bootlid Lock Actuator	Deformed	489 ✓
Bootlid Inner Trim Board	torn	525 ✓

SGX 6628R.

Bootlid Inner Trim Board clips ^{new} 30(SN) ✓

Bootlid Lower Inner Garnish. ^{Del'd} 275. ✓

Bootlid Outer Chrome Moulding. ^{could} 267 ✓

Bootlid Hinge x 02 ^{new} 285x2=570 +

Bootlid Hinge Cover x 02 ^{new} 58x2=116 +

Bootlid Operer Switch. ^{Del'd} 198 ✓

Bootlid Weatherstripe. ^{ut} 292 ✓

Mercedes Benz Logo ^{new} 70 ✓

E200 Wording. ^{new} 93. ✓

Rear Fender Inner Trim Board x 02 ^{new} 455x2=910 +

Rear Fender Inner Trim Board clips. ^{new} 60(SN) +

Rear Fender Top Garnish x 02 ^{Del'd} 52x2=104 ✓

Rear Fender Top Garnish clips. ^{new} 40(SN) ✓

Spere Tyre Panel Top Board. ^{Del'd} 710. ✓

13523. S.N: 260

1217070.

SGX 6628R.

Panel Beating
Spray Painting,
Wiring.

To apply tuff coat

To remove reverse sensor

To remove upholstery.

To transfer bootlid fittings

To perform diagnostic test.

~~1400~~ 1000

~~1200~~ 1000

~~100~~ 50

~~150~~ 80

~~100~~ 50

~~150~~ 80

~~150~~ 80.

~~300~~ 150. 2490

Total: 14920.70

L/S: 11.9K. ✓

07 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: