4/3/23, 8:45 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22008896/KVY3M4

Date: 03/04/2023

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001379081

Claimant Vehicle No: SLJ6850D Insured Vehicle No: SCP6883J

Date of Loss: 21/08/2022 Nature of Claim: TP Claim No: 284088

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLJ6850D

Make & Model: MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A) Engine No: P520375242

Reg. Date: 21/12/2016 (Man. Year: 2016) Chassis No: JM6BM42A8G0346404

Colour: Metallic Black Odometer: 136448 km

Engine Capacity: 1496 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	750.00	480.00	270.00	36.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	750.00	480.00	270.00	36.00
+ GST 8.00/8.00% (S\$)	60.00	38.40	21.60	36.00
Nett Amount (S\$)	810.00	518.40	291.60	36.00

INSPECTION

Date of Assignment: 09/09/2022

Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 14/12/2022 Inspected At: Blk 1019 #01-374/382, Yishun Industrial Park A

Singapore 768761

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/3/23, 8:45 AM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Apr 2023)

Parts: 143 MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLJ6850D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount	
Lab	our Items				
1	REMOVE & REFIX FRT BUMPER & ATTACHMENTS,HEADLAMP & REALIGN THE SAME	New	200.00	80.00	
2	PUTTY & RESPRAY FRT BUMPER & ATTACHMENTS,FRT RH FENDER & ALL AFFECTED AREAS	New	550.00	400.00	
	Gross Labour	Cost (S\$)	750.00	480.00	
	Report was unsubmitted during this print-out.				

< END OF ESTIMATES >