

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008899/UQY3Q2**Date:** 17/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00012682101		
Claimant Vehicle No :	SLF7537Z	Insured Vehicle No :	SFT6644B		
Date of Loss:	02/09/2022	Nature of Claim:	TP	Claim No:	SNM22D206321/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF7537Z	Engine No:	L15B3533652
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Chassis No:	GK81003043
Reg. Date:	08/09/2016 (Man. Year: 2015)	Odometer:	83653 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45 R17	Rear Tyre Size:	205/45 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,517.92	1,670.72	5,847.20	77.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,210.00	1,570.00	1,640.00	51.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,727.92	3,240.72	7,487.20	69.79
Approved Total (Overridden) (\$\$)		2,550.00		
(\$\$)	10,727.92	2,550.00	8,177.92	76.23
+ GST 7.00/7.00% (\$\$)	750.95	178.50	572.45	76.23
Nett Amount (\$\$)	11,478.87	2,728.50	8,750.37	76.23

INSPECTION

Date of Assignment:	09/09/2022		
Date Inspected:	06/12/2022	Inspected At:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Feb 2023)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF7537Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deep Cut	1,150.60 FL	*1,150.60 FL
2	2		*REAR BUMPER SIDE HOLDER -LH /RH	Not Necessary	60.20 FL	*- FL
3	10		*REAR BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
4	1		*REAR FENDER -RH	Repair	1,010.90 FL	*- FL
5	1		*REAR FENDER COWLING -RH	Not Necessary	99.00 FL	*- FL
6	10		*REAR FENDER COWLING CLIPS -RH	Not Necessary	39.00 FL	*- FL
7	1		*REAR DOORS-RH	Dented / Bent	799.50 FL	*799.50 FL
8	1		*SET REAR DOORS STICKER -RH	Necessary	21.00 FL	*21.00 FL
9	1		*REAR DOOR RUBBER -RH	Necessary	78.30 FL	*78.30 FL
10	1		*FRONT FENDER -RH	Repair	517.50 FL	*- FL
11	1		*FRONT FENDER COWLING -RH	Not Necessary	120.50 FL	*- FL
12	10		*FRONT FENDER COWLING CLIPS -RH	Not Necessary	39.00 FL	*- FL
13	1		*FRONT BUMPER	Repair	1,250.50 FL	*- FL
14	2		*FRONT BUMPER SIDE HOLDER-LH/RH	Not Necessary	26.00 FL	*- FL
15	10		*FRONT BUMPER CLIPS	Not Necessary	39.00 FL	*- FL
16	1		*FRONT RIM -RH (CUT)	Not Consistent With The Impact	431.00 FL	*- FL
17	1		*FRONT RIM WHEEL BEARING -RH	Not Necessary	168.00 FL	*- FL
18	1		*REAR RIM -RH (CUT)	Not Consistent With The Impact	431.00 FL	*- FL
19	1		*REAR RIM WHEEL BEARING -RH	Not Necessary	321.00 FL	*- FL
20	1		*SET REAR FENDER GLASS MOULDING -RH	Not Necessary	131.00 FL	*- FL
21	1		*HEAD LAMP UNIT-RH	Not Necessary	2,315.60 FL	*- FL
22	1		*HEAD LAMP LOWER RETAINER -RH	Not Necessary	59.80 FL	*- FL
23	1		*FRONT FENDER STICKER-RH	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,347.40	2,088.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,829.48	417.68
Total Parts (\$\$)	7,517.92	1,670.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS ,REMOVE ,REPLACE ACCIDENT PARTS	New	800.00	400.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS (PEARL)	New	2,000.00	1,000.00
3	TO CHECK WIRING	New	40.00	20.00
4	TO TRANSFER DOOR & DOOR FITTINGS	New	80.00	60.00
5	TO TUFF-KOTE	New	120.00	30.00
6	TO 4 WHEEL ALIGNMENT	New	80.00	60.00
7	TO REMOVE,REPLACE 2 RIM & TYRE BALANCING	New	90.00	0.00
Gross Labour Cost (\$\$)			3,210.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >