



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI21007068/Dqy3e2-1	
			Date: 31/01/2023	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	GBJ 5276L	Veh. Inspected	SMR 276Y
	Policy No.	DMCVSNA00069252101	Coverage (\$)	0.00
	Claim No.	SNM21D203540/C2	Excess (\$)	0.00
	Assign From	IRENE TAY	Assign Date	09/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HARRIER	c.c	2362
	Engine No.	HIDDEN	Year of Reg.	2007
	Chassis No.	ACU300071947	Colour	SILVER
	Odometer	214844 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/65 R17	TOYO	6 mm
	L/H Front Tyre	225/65 R17	TOYO	6 mm
	R/H Rear Tyre	225/65 R17	TOYO	6 mm
	L/H Rear Tyre	225/65 R17	TOYO	6 mm
4. Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information				
	Accident Date	23/06/2021	Inspection Date	28/06/2022
	Survey held at	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	