

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22008907/AVCM4**Date:** 30/12/2022**REFERENCE**

Insured/Claimant: CHUA MENG HUI SEBASTIAN Policy No: 7220014670
Date of Loss: 07/09/2022 Nature of Claim: OD Claim No: 1016688902SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJC7028R**
Make & Model: AUDI A3 SPORTBACK, 1.5 TFSI S TRONIC (A) Engine No: DFY305285
Reg. Date: 12/02/2022 (Man. Year: 2021) Chassis No: WAUZZZGY5NA025908
Colour: White Odometer: 13816 km
Engine Capacity: 1498 cc
Market Value/New Car Price: S\$195,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,209.00	5,464.72	7,744.28	58.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,352.00	4,412.00	2,940.00	39.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,561.00	9,876.72	10,684.28	51.96
- Excess (\$\$)	3,400.00	3,400.00	0.00	0.00
(\$\$)	17,161.00	6,476.72	10,684.28	62.26
+ GST 7.00/7.00% (\$\$)	1,201.27	453.37	747.90	62.26
Nett Amount (\$\$)	18,362.27	6,930.09	11,432.18	62.26

INSPECTION

Date of Assignment: 12/09/2022
Date Inspected: 09/09/2022 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER - LH	Dented	1,241.00 FS	*992.80 FS
2	3		*FRONT FENDER RIVET	Necessary	12.00 FS	*9.12 FS
3	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	32.00 FS	*- FS
4	2		*FRONT FENDER BRACKET - LH / RH	Not Necessary	81.00 FS	*- FS
5	1		*FRONT FENDER BRACKET - LH	Not Necessary	31.00 FS	*- FS
6	1		*FRONT FENDER BRACE - LH	Not Necessary	98.00 FS	*- FS
7	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	121.00 FS	*- FS
8	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	183.00 FS	*- FS
9	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	22.00 FS	*- FS
10	1		*HEADLIGHT - LH	Not Necessary	4,084.00 FS	*- FS
11	1		*FRONT DOOR - LH	Dented	3,089.00 FS	*2,471.20 FS
12	1		*FRONT OUTER DOOR SEAL - LH	Necessary	179.00 FS	*142.80 FS
13	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	343.00 FS	*- FS
14	1		*FRONT DOOR CATCH - LH	Not Necessary	93.00 FS	*- FS
15	1		*FRONT WING MIRROR MOUNTING - LH	Damaged	876.00 FS	*700.80 FS
16	1		*FRONT WING MIRROR CAP - LH	Repair	180.00 FS	*- FS
17	1		*FRONT WING MIRROR GLASS - LH	Not Necessary	705.00 FS	*- FS
18	1		*FRONT ALUMINIUM RIM - LH	Cut	1,435.00 FS	*1,148.00 FS
19	1		*FRONT ALUMINIUM RIM RUBBER VALVE	Not Necessary	4.00 FS	*- FS
20	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$)	13,209.00	5,464.72
-------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	360.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	350.00	280.00
4	TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW LHS FRONT FENDER AND LHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,200.00	1,500.00
5	TO RESPRAY LHS FRONT FENDER, LHS FRONT DOOR AND LHS WING MIRROR COVER	New	2,500.00	1,800.00
6	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			7,352.00	4,412.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >