



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBF 7255E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HEAD COWLING	CUT	165.00	165.00
1	FRONT SIGNALS LH	CUT	66.00	66.00
1	HANDLE BAR RH	BENT	130.00	130.00
1	HANDLE BAR BALANCER RH	CUT	15.00	15.00
1	SIDE MIRROR RH	CUT	95.00	95.00
1	STICKER	NECESSARY	66.00	66.00
1	GEAR PEDAL	BENT	77.00	77.00
1	FRONT FOOT REST RH	BENT	60.00	60.00
1	EXHAUST MUFFLER COVER	CUT	77.00	77.00
1	SIDE FAIRING RH	CUT	165.00	165.00
	LESS 10% DISCOUNT		-	-91.60
			916.00	824.40
	<u>LABOUR</u>			
	TOWING.		40.00	40.00
	LABOUR.		450.00	280.00
			490.00	320.00
GRAND TOTAL			1,406.00	1,144.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				900.00

Report Ref No. CS/SPF22008913/Eqy3m4

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$900-\$1,000

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.