



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YM 9547R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	TMA LOWER TAILLAMPS - LOWER	BROKEN	354.80	354.80
2	TMA LOWER TAILLAMPS - UPPER / TOP	BROKEN / DAMAGED	354.80	354.80
1	TMA LOWER NUMBER PLATE LAMP	CRUSHED	88.90	88.90
	LESS 25% DISCOUNT		-	-199.63
			798.50	598.87
	<u>SPECIAL NETT ITEMS</u>			
2	TMA TAILLAMP UPPER BRACKETS (SN)	DAMAGED	100.00	100.00
2	TMA TAILLAMP LOWER BRACKETS (SN)	DAMAGED	100.00	100.00
1	REAR NUMBER PLATE - TMA UPPER (SN)	DAMAGED	30.00	30.00
1	REAR NUMBER PLATE - TMA LOWER (SN)	DAMAGED	30.00	30.00
1	TMA REFLECTIVE STICKER - TOP (SN)	NECESSARY	200.00	160.00
1	TMA REFLECTIVE STICKER - REAR (SN)	NECESSARY	600.00	400.00
2	TMA REFLECTIVE STICKERS - SIDE (SN)	NECESSARY	160.00	140.00
1	TMA DANGER KEEP CLEAR STICKER (SN)	NECESSARY	300.00	250.00
1	TMA "60KM/H" STICKER - UPPER (SN)	NECESSARY	20.00	16.00
1	TMA "60KM/H" STICKER - LOWER (SN)	NECESSARY	20.00	16.00
			1,560.00	1,242.00
	<u>LABOUR</u>			
	LABOUR CHARGES TO REPAIR, PANEL BEAT, STRAIGHTEN AND RE-ALIGN TMA TO VEHICLE AND REPLACE THE ABOVE-MENTIONED PARTS.		900.00	500.00
	TO RE-WIRE TMA, CHECK WIRING FUNCTION.		80.00	20.00
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT THE AFFECTED AREAS.		600.00	400.00
	TO APPLY RUST-PROOFING ON REPAIRED / REPLACED PANEL.	NOT NECESSARY	80.00	-
	TOWING CHARGES.	NOT NECESSARY	300.00	-
			1,960.00	920.00
	GRAND TOTAL		4,318.50	2,760.87

Report Ref No. CS1/LAW22008915/Kqce2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (EXCLUDE TMA)			2,200.00
--	--	--	----------

Report Ref No. CS1/LAW22008915/Kqce2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YM 9547R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>SPECIAL NETT ITEMS</u>			
	LED BEACON LIGHT (SN)	SERVICEABLE	250.00	-
			250.00	-
	<u>LABOUR</u>			
	TO SUPPLY & INSTALL BARRIER SYSTEMS TYPE TRUCK MOUNTED ALTERNUATOR (TMA) FOR THE VEHICLE YM 9547R. (S\$46,500.00 LESS 5%=S\$44,175.00).		44,175.00	18,312.50
	MODIFICATION OF BACK UP ASSEMBLY.	NOT NECESSARY	2,000.00	-
	REPAIR / REALIGN QUICK MOUNT BRACKET.		1,750.00	800.00
	LABOUR COST FOR DISMANTLE & REMOVE DAMAGED TMA.	NOT NECESSARY	2,000.00	-
			49,925.00	19,112.50
GRAND TOTAL			50,175.00	19,112.50
RECOMMENDED COST OF REPAIRS (TMA ONLY)				19,112.50

Report Ref No. CS1/LAW22008915/Kqce2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.