

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008919/UYA3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070145414
Claimant Vehicle No :	SJJ320E	Insured Vehicle No :	SGA9007J
Date of Loss:	25/08/2022	Nature of Claim:	TP
		Claim No:	6970900610SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ320E	Engine No:	1AZE114910
Make & Model:	TOYOTA CAMRY, 2.0 ABS AIRBAG (A)	Chassis No:	MR053BK4107034741
Reg. Date:	30/08/2008 (Man. Year: 2008)	Odometer:	179164 km
Colour:	Silver		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,689.75	1,302.82	2,386.93	64.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,630.00	1,080.00	1,550.00	58.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,319.75	2,382.82	3,936.93	62.30
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	6,319.75	1,900.00	4,419.75	69.94
+ GST 7.00/7.00% (S\$)	442.38	133.00	309.38	69.94
Nett Amount (S\$)	6,762.13	2,033.00	4,729.13	69.94
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,435.00		

INSPECTION

Date of Assignment:	12/09/2022		
Date Inspected:	12/09/2022	Inspected At:	Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT COVER	Repair	1,018.00 FL	*- FL
2	1		*BOOT LOGO	Not Necessary	82.00 FL	*- FL
3	1		*BOOT LOCK	Serviceable	388.00 FL	*- FL
4	1		*BOOT WEATHERSTRIP	Not Necessary	219.00 FL	*- FL
5	1		*REAR BUMPER	Dented / Deformed	769.00 FL	*681.10 FL
6	2		*REAR BUMPER SIDE RETAINE	Bent / Necessary	188.00 FL	*188.00 FL
7	1		*REAR BUMPER REINFORCEMENT	Bent	398.00 FL	*398.00 FL
8	1		*REAR END PANEL	Repair	676.00 FL	*- FL
9	1		*REAR END PANEL GARNISH	Not Necessary	485.00 FL	*- FL
10	1		*BOOT EMBLEM (CAMRY)	Necessary	78.00 FL	*78.00 FL
11	1		*BOOT EMBLEM (2.0)	Necessary	72.00 FL	*72.00 FL
12	1		*REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
13	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
14	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
15	1		*REAR END PANEL GARNISH CLIP	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,783.00	1,657.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,093.25	354.28
Total Parts (\$\$)	3,689.75	1,302.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND LIGHT SYSTEM	New	50.00	20.00
2	TO TRANSFER BOOT LID PARTS	New	120.00	0.00
3	TO FIT REVERSE SENSOR IN BUMPER	New	50.00	50.00
4	TO CONDUCT WATERTEST AT BOOT COMPARTMENT	New	50.00	0.00
5	TO RUSTROOF ON DAMAGED PARTS	New	180.00	0.00
6	TO APPLY BODY SEALANT ON BODY JOINTS	New	180.00	0.00
7	TO REMOVE /REFIT GARNISH AND TRIMS TO FACILITATE REPAIRS	New	200.00	60.00
8	TO REPAIR INNER PANEL ,ACCIDENT DAMAGE AREA CUT /REWELD REAR END PANEL,REPLACEMENT OF PARTS AND ALIGN THE SAME	New	900.00	400.00
9	TO PUTTY AND RESPRAY ACCIDENT DAMAGE AREA	New	900.00	550.00
Gross Labour Cost (S\$)			2,630.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >