

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122008920/TCY3Q2**Date:** 14/07/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SKR8773A **Insured Vehicle No :** GBL8108J

Date of Loss: 01/09/2022 Nature of Claim: TP Claim No: CDMCG22001829

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKR8773A**

Make & Model: VOLVO S60, 2.0 T5 (A) Engine No: B4204T111117413

Reg. Date: 16/03/2015 (Man. Year: 2014) Chassis No: YV1FS40LDF2348244

Colour: Beige Odometer: 155175 km

Engine Capacity: 1969 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45 R17 Rear Tyre Size: 235/45 R17

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,662.50	2,208.00	12,454.50	84.94
Miscellaneous Items	40.00	40.00	0.00	0.00
Labour	830.00	280.00	550.00	66.27
Paintwork Labour	680.00	250.00	430.00	63.24
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,212.50	2,778.00	13,434.50	82.87
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	16,212.50	2,200.00	14,012.50	86.43
+ GST 7.00/8.00% (S\$)	1,134.88	176.00	958.88	84.49
Nett Amount (S\$)	17,347.38	2,376.00	14,971.38	86.30

INSPECTION

Date of Assignment: 12/09/2022 Present Location: Kan Fook Sing Motor Workshop (Defu)
BLK.8 JTC DEFU INDUSTRIAL CITY

Date Inspected: 23/09/2022 Inspected At: #04-29 DEFU SOUTH STREET 1
SINGAPORE 533758

Estimated Period of Repair: 3.0 days Repairer: Kan Fook Sing Motor Workshop (Defu)

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jul 2023)
Parts:	143	VOLVO S60 2.0 T5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR8773A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (WCP)	Not Necessary	1,250.00 F	*- F
2	1		*FRONT BONNET LOCK RH (WCP)	Not Necessary	150.00 F	*- F
3	1		*FRONT BONNET LOCK LH (WCP)	Not Necessary	150.00 F	*- F
4	1		*FRONT SUPPORT PANEL (WCP)	Not Necessary	2,200.00 F	*- F
5	1		*FRONT GRILLE (WCP)	Cracked	420.00 F	*420.00 F
6	1		*FRONT BUMPER (WCP)	Deformed	2,300.00 F	*1,500.00 F
7	1		*FRONT BUMPER FOAM (WCP)	Not Necessary	230.00 F	*- F
8	1		*FRONT BUMPER REINFORCEMENT (WCP)	Not Necessary	750.00 F	*- F
9	1		*FRONT BUMPER LOWER GRILLE (WCP)	Not Necessary	100.00 F	*- F
10	1		*FRONT HEADLAMP RH (WCP)	Not Necessary	2,600.00 F	*- F
11	1		*FRONT HEADLAMP LH (WCP)	Not Necessary	2,600.00 F	*- F
F=Franchise part.						
Sub Total (\$\$)					12,750.00	1,920.00
+ Margin on L,N Items 15.00/15.00% (\$\$)					1,912.50	288.00
Total Parts (\$\$)					14,662.50	2,208.00
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT NUMBER PLATE (BENT)	40.00	40.00
Sub Total (\$\$)			40.00	40.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	SPRAYPAINTING CHARGES	New	680.00	250.00
Labour Items				
2	TO CHECK WIRING SYSTEM	New	50.00	30.00
3	TO REMOVE/REFIT/REFILL AIR CON GAS	New	100.00	0.00
4	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	680.00	250.00
Gross Labour Cost (\$\$)			1,510.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >