

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008921/UPA3Q2**Date:** 08/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070009410
Claimant Vehicle No :	SMK9995H	Insured Vehicle No :	SMR6578L
Date of Loss:	06/09/2022	Nature of Claim:	TP
		Claim No:	3147394470SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK9995H	Engine No:	26492030349834
Make & Model:	MERCEDES-BENZ E200, 2.0 (A)	Chassis No:	W1K2130802A909321
Reg. Date:	15/04/2021 (Man. Year: 2020)	Odometer:	25835 km
Colour:	Blue		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,098.20	4,154.50	4,943.70	54.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	1,210.00	1,570.00	56.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,878.20	5,364.50	6,513.70	54.84
+ GST 7.00/7.00% (S\$)	831.47	375.52	455.95	54.84
Nett Amount (S\$)	12,709.67	5,740.02	6,969.65	54.84
+ Car Rental (3.0 x S\$120.00/day + 7.00% GST) (S\$)		385.20		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,127.22		

INSPECTION

Date of Assignment:	12/09/2022	
Date Inspected:	12/09/2022	Inspected At: Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LOGO	Not Necessary	105.00 FL	*- FL
2	1		*BOOT EMBLEM E250	Not Necessary	180.00 FL	*- FL
3	1		*REAR BUMPER	Dented / Deformed	2,667.00 FL	*2,412.00 FL
4	2		*REAR BUMPER SIDE RETAINER	Not Necessary	364.00 FL	*- FL
5	1		*REAR BUMPER CENTER BRACKET	Cracked	256.00 FL	*256.00 FL
6	1		*REVERSE SENSOR (6 PCS)	Shorted (2 PCS ONLY)	2,196.00 FL	*610.00 FL
7	6		*REVERSE SENSOR ORING	Necessary	102.00 FL	*102.00 FL
8	1		*REAR BUMPER LOWER LIP	Grazed	680.00 FL	*466.00 FL
9	6		*REVERSE SENSOR BRACKET	Necessary	390.00 FL	*168.00 FL
10	1		*REAR BUMPER LOWER LIP CHROME	Cracked	697.00 FL	*402.00 FL
11	1		*O/S REAR BUMPER REFLECTOR	Not Necessary	142.00 FL	*- FL
12	1		*REAR BUMPER REINFORCEMENT	Repair	1,555.00 FL	*- FL
13	1		*O/S REAR EXHAUST CHROME	Serviceable	375.00 FL	*- FL
14	1		*REAR BUMPER CLIP	Necessary	60.00 FS	*50.00 FS
15	1		*REAR BUMPER RIVET	Necessary	80.00 FS	*50.00 FS
16	1		*REAR BUMPER LOWER LIP CLIP	Not Necessary	60.00 FS	*- FS
17	1		*REAR BUMPER LOWER RIVETS	Not Necessary	80.00 FS	*- FS
18	1		*O/S REAR EXHAUST CHROME BRACKET	Twisted	89.00 FL	*89.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,078.00	4,605.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	979.80	450.50
Total Parts (\$\$)	9,098.20	4,154.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR PORTION WIRING	New	50.00	20.00
2	TO FIT REVERSE SENSOR IN BUMPER	New	50.00	50.00
3	TO RESET CLEARANCE SONAR USING DIAGNOSTIC SCANNER	New	400.00	80.00
4	TO RUST PROOF PANELS	New	200.00	0.00
5	TO REMOVE/REFIT GARNISH AND TRIMS TO FACILITATE REPAIRS	New	280.00	60.00
6	TO REPAIR INNER PANEL ACCIDENT DAMAGE AREA ,REPLACEMENT OF PARTS AND ALIGN THE SAME	New	600.00	400.00
7	TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA	New	900.00	600.00
8	TO REPAIR AND RE-ALIGN EXHAUST	New	300.00	0.00
Gross Labour Cost (S\$)			2,780.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >