

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22008923/ENY3Q2**Date:** 05/10/2022**REFERENCE**

Insured/Claimant:	CHUA WEN BIN	Policy No:	SP2002032832	
Date of Loss:	08/09/2022	Nature of Claim:	OD	Claim No: 202222006615JK

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA4452G		
Make & Model:	HYUNDAI CN7 AVANTE 1.6, 1.6 (A)	Engine No:	G4FMMU047565
Reg. Date:	24/06/2021 (Man. Year: 2021)	Chassis No:	KMHLN41ETNU212384
Colour:	Grey	Odometer:	23018 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$110,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R15	Rear Tyre Size:	205/55 R15
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,035.76	6,703.68	332.08	4.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,770.00	5,400.00	370.00	6.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,805.76	12,103.68	702.08	5.48
+ GST 7.00/7.00% (S\$)	896.40	847.26	49.14	5.48
Nett Amount (S\$)	13,702.16	12,950.94	751.22	5.48

INSPECTION

Date of Assignment:	12/09/2022		
Date Inspected:	14/09/2022	Inspected At:	Komoco Motors Pte Ltd (Bukit Merah) 253 Alexandra Road #01-01 Singapore 159936
Estimated Period of Repair:	12.0 days		

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Oct 2022)
Parts:	143	HYUNDAI CN7 AVANTE 1.6 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA4452G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	10		*BUMPER CLIP	Not Necessary	12.00 FL	*- FL
2	1		*PANEL ASSY FENDER ,RH	Dented	1,227.70 FL	*1,227.70 FL
3	1		*INSULATOR -FENDER RH	Necessary	47.20 FL	*47.20 FL
4	1		*PANEL ASSY -FRONT DOOR ,RH	Dented	2,147.90 FL	*2,147.90 FL
5	2		*HINGE ASSY -FRONT DOOR UPPER ,RH	Not Necessary	59.00 FL	*- FL
6	1		*HANDLE ASSY -DOOR OUTSIDE ,RH	Cut	179.10 FL	*179.10 FL
7	1		*GUARD ASSY -FRONT WHEEL RH	Broken	94.60 FL	*94.60 FL
8	1		*GUARD ASSY -FRONT MUD ,RH	Broken	23.00 FL	*23.00 FL
9	1		*MIRROR ASSY -OUTSIDE RR VIEW ,RH	Broken	638.60 FL	*638.60 FL
10	1		*PANEL -SIDE SILL OTER ,RH	Dented	1,799.60 FL	*1,799.60 FL
11	1		*GARNISH ASSY ,DR FRAME RH	Not Necessary	30.00 FL	*- FL
12	1		*MOULDING ASSY -FRT DR FRAME ,RH	Bent	41.70 FL	*41.70 FL
13	1		*W/STRIPP ASSY -FR DR BELT O/S RH	Not Necessary	81.60 FL	*- FL
14	2		*PAD -FR DR QUADRANT ANTINOISE,L	Not Necessary	5.40 FL	*- FL
15	1		*PANEL ASSY -REAR DOOR ,RH	Dented	2,147.90 FL	*2,147.90 FL
16	1		*HINGE ASSY ,REAR DORO UPPER RH	Not Necessary	45.90 FL	*- FL
17	1		*HINGE ASSY -FR DR RH	Not Necessary	36.10 FL	*- FL
18	1		*GARNISH ASSY -RR DR FR FRAME ,RH	Not Necessary	30.00 FL	*- FL
19	1		*W/STRIP ASSY -RR DR BELT O/S RH	Not Necessary	85.10 FL	*- FL
20	1		*MOULDING ASSY -RR DR FRAME ,RH	Bent	32.30 FL	*32.30 FL
21	1		*GARNISH ASSY -RR DR RR FRAME ,RH	Not Necessary	30.00 FL	*- FL
					Sub Total (\$\$)	8,794.70 8,379.60
					- List Item Discount on L Items 20.00/20.00% (\$\$)	1,758.94 1,675.92
					Total Parts (\$\$)	7,035.76 6,703.68

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CARRY OUT ACCIDENT BODY REPAIR	New	2,280.00	2,470.00
2	COMPLETE PUTTY AND SPRAY PAINT ALL AFFECTED AREAS	New	2,040.00	1,860.00
3	TO SUPPLY DOOR SEALANT	New	200.00	200.00
4	TO REPAIR FENDER APRON BRACKET ()	New	380.00	0.00
5	TO TRANSFER DOOR WIRING & MECHANISM	New	300.00	300.00
6	TO R&I SEAT & CARPET TO FACILITATE REPAIR	New	570.00	570.00
Gross Labour Cost (\$)			5,770.00	5,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >