

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22008924/ACY3Q2
Date: 25/10/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00015762100
Claimant Vehicle No :	SLB9124P	Insured Vehicle No :	SND7000S
Date of Loss:	06/09/2022	Nature of Claim:	TP
		Claim No:	SNM22D206429/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB9124P	Engine No:	L15B4025736
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11105734
Reg. Date:	26/04/2016 (Man. Year: 2015)	Odometer:	82281 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,080.64	3,067.28	1,013.36	24.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	880.00	470.00	34.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,430.64	3,947.28	1,483.36	27.31
Approved Total (Overridden) (\$\$)		3,150.00		
	5,430.64	3,150.00	2,280.64	42.00
+ GST 7.00/7.00% (\$\$)	380.14	220.50	159.64	42.00
Nett Amount (\$\$)	5,810.78	3,370.50	2,440.28	42.00

INSPECTION

Date of Assignment:	09/09/2022	
Date Inspected:	27/09/2022	Inspected At: Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58 Singapore 408717
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Oct 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB9124P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	821.40 FL	*821.40 FL
2	1		*FRONT BUMPER SIDE HOLDER -LH & RH	N/S Damaged	53.00 FL	*26.50 FL
3	1		*FRONT BUMPER REINFORCEMENT	Dented	321.00 FL	*321.00 FL
4	1		*FRONT BUMPER FOG LAMP -LH	Not Necessary	327.20 FL	*- FL
5	1		*FRONT BUMPER FOG LAMP COVER -LH	Deformed	85.20 FL	*85.20 FL
6	1		*FRONT BUMPER LOWER SPOILER	Repair	386.20 FL	*- FL
7	1		*FRONT GRILLE	Not Necessary	351.80 FL	*- FL
8	1		*FRONT GRILLE OUTER MOULDING	Cut	283.90 FL	*283.90 FL
9	1		*FRONT GRILLE LOGO	Necessary	35.90 FL	*35.90 FL
10	1		*HEADLAMP LH	Cracked	1,859.40 FL	*1,859.40 FL
11	1		*HEADLAMP LOWER BRACKET -LH	Cracked	39.40 FL	*39.40 FL
12	1		*AIR CON CONDENSER SIDE GUIDE -LH	Deformed	36.40 FL	*36.40 FL
13	1		*FRONT NUMBER PLATE	Not Necessary	30.00 FS	*- FS
14	1		*FRONT NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
15	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
16	1		*FRONT BUMPER SENSOR	Damaged	280.00 FS	*200.00 FS
17	1		*SET FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
18	1		*SET AIR CON CONDENSER SIDE GUIDE CLIPS	Necessary	10.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,000.80	3,769.10
- List Item Discount on L Items 20.00/20.00% (S\$)	920.16	701.82
Total Parts (S\$)	4,080.64	3,067.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING OUT FRONT PORTION & RENEW ABOVE PARTS	New	700.00	400.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	500.00	400.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO REMOVE FRONT BUMPER SENSOR	New	100.00	50.00
Gross Labour Cost (\$\$)			1,350.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >