

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008927/EQY3Q2**Date:** 30/03/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00033882200
Claimant Vehicle No :	SLG6996H	Insured Vehicle No :	GQ9369E
Date of Loss:	07/09/2022	Nature of Claim: TP	Claim No: SNM22D206413/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG6996H	Engine No:	G4FGKU024460
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS (A)	Chassis No:	KMHD841CMLU034880
Reg. Date:	15/06/2020 (Man. Year: 2019)	Odometer:	50280 km
Colour:	Black		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,794.40	1,864.00	1,930.40	50.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	1,130.00	850.00	42.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,774.40	2,994.00	2,780.40	48.15
+ GST 8.00/8.00% (S\$)	461.95	239.52	222.43	48.15
Nett Amount (S\$)	6,236.35	3,233.52	3,002.83	48.15

INSPECTION

Date of Assignment:	11/09/2022	
Date Inspected:	12/09/2022	Inspected At: Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3 Singapore 159722
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Mar 2023)
Parts: 143	HYUNDAI AD AVANTE 1.6 GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLG6996H)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Dented	1,227.00 FL	*1,227.00 FL
2	1		*FRONT FENDER COWLING LH	Crushed	185.00 FL	*185.00 FL
3	10		*FRONT FENDER COWLING CLIPS	Necessary	31.20 FS	*20.00 FS
4	1		*FRONT FENDER SIGNAL	Not Necessary	68.00 FL	*- FL
5	1		*FRONT WIPER GARNISH	Not Necessary	478.00 FL	*- FL
6	1		*FRONT SHOCK ABSORBER LH	Bent	372.00 FL	*372.00 FL
7	1		*FRONT SHOCK ABSORBER MOUNTING LH	Not Necessary	126.00 FL	*- FL
8	1		*FRONT KNUCKLE ARM LH	Not Necessary	412.00 FL	*- FL
9	1		*FRONT KNUCKLE BEARING LH	Jammed	396.00 FL	*396.00 FL
10	1		*FRONT LOWER ARM	Not Necessary	298.00 FL	*- FL
11	1		*FRONT STG RACK END LH	Not Necessary	116.00 FL	*- FL
12	1		*FRONT STG TID ROD END LH	Not Necessary	104.00 FL	*- FL
13	1		*FRONT BUMPER RETAINER LH	Not Necessary	47.00 FL	*- FL
14	1		*FRONT BUMPER (NPA)	Repair	0.00 FL	*- FL
15	1		*FRONT BONNET (NPA)	Repair	0.00 FL	*- FL
16	1		*FRONT FENDER INNER PANEL LH (NPA)	Repair	0.00 FL	*- FL
17	1		*FRONT DOOR LH (NPA)	Repair	0.00 FL	*- FL
18	1		*HEADLAMP (NPA)	Repair	0.00 FL	*- FL
19	1		*FRONT ALLOY WHEEL LH (LOCAL REPAIR)	Cut	450.00 FS	*100.00 FS
20	1		*FRONT TYRE LH	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,560.20	2,300.00
- List Item Discount on L Items 20.00/20.00% (\$)	765.80	436.00
Total Parts (\$)	3,794.40	1,864.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT & WELD ,TO REPAIR FRONT DOOR LH ,BONNET ,INNER PANEL LH ,FRONT BUMPER TO REMOVE & REFIX DAMAGED PARTS ,STRAIGHTEN & REALIGN AFFECTED AREAS	New	750.00	300.00
2	TO SPRAY AFFECTED AREAS ,BONNET ,FRONT FENDER LH ,FRONT DOOR LH ,FRONT FENDER LH & AFFECTED AREAS	New	850.00	600.00
3	TO REMOVE & REFIX FRONT UNDER CARRIAGE & FRONT SUSPENSION	New	180.00	120.00
4	TO CHECK WHEEL ALIGNMENT	New	100.00	80.00
5	TO DIAGNOSTIC WERE NECESSARY	New	100.00	30.00
			Gross Labour Cost (S\$)	1,980.00
				1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >