

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008929/SNY3Q2**Date:** 14/12/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00249792100

Claimant Vehicle No : SND5761S **Insured Vehicle No :** SKN7882X

Date of Loss: 08/09/2022 Nature of Claim: TP Claim No: SNM22D206430/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SND5761S**

Make & Model: HONDA SHUTTLE, 1.5 (A) Engine No: LEB7605995

Reg. Date: 11/01/2022 (Man. Year: 2021) Chassis No: GP72204915

Colour: Grey Odometer: 45518 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Ecopia 6 mm Rear Left Side: Ecopia 7 mm

Front Right Side: Ecopia 6 mm Rear Right Side: Ecopia 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,105.70	1,058.00	8,047.70	88.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,310.00	930.00	3,380.00	78.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,415.70	1,988.00	11,427.70	85.18
+ GST 7.00/7.00% (S\$)	939.10	139.16	799.94	85.18
Nett Amount (S\$)	14,354.80	2,127.16	12,227.64	85.18

INSPECTION

Date of Assignment: 12/09/2022

Date Inspected: 03/10/2022 Inspected At: Xin Yun Auto Private Limited (HQ)
1 Kaki Bukit Avenue 6, #01-59 Autobay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Dec 2022)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SND5761S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	1,233.20 F	*930.00 FL
2	1		*BUMPER BRACKET	N/S Necessary	190.00 F	*100.00 FL
3	2		*BUMPER REFLECTOR	Not Necessary	220.00 F	*- FL
4	1		*REAR END PANEL	Repair	950.00 F	*- FL
5	1		*TAILGATE	Repair	1,800.00 F	*- FL
6	1		*TAILGATE INNER TRIM COVER	Not Necessary	380.00 F	*- FL
7	1		*TAILGATE LOCK	Not Necessary	320.00 F	*- FL
8	2		*TAILGATE ABSORBER	Not Necessary	600.00 F	*- FL
9	1		*FRONT BUMPER TOW COVER	Not Necessary	95.00 F	*- FL
10	1		*TAILGATE RUBBER SEAL	Torn	250.00 F	*230.00 FL
11	1		*TOP COVER TRIM	Not Necessary	280.00 F	*- FL
12	1		*MIDDLE CHROME ASSY	Not Necessary	457.50 F	*- FL
13	1		*TAILGATE LIGHT LEFT	Not Necessary	850.00 F	*- FL
14	1		*TAILGATE LIGHT RIGHT	Not Necessary	850.00 F	*- FL
15	10		*BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
16	8		*FENDER INNER BOARD CLIPS	Not Necessary	40.00 FS	*- FS
17	6		*MIDDLE CHROME MOULDING CLIPS	Not Necessary	40.00 FS	*- FS
18	6		*TOP GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
19	8		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
20	1		*FRONT NO PLATE WITH CASHING	Not Necessary	80.00 FS	*- FS
21	1		*SENSOR	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,105.70	1,310.00
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	252.00
Total Parts (\$)	9,105.70	1,058.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECKING REAR WIRING HARNESS AND LIGHTING SYSTEM FOR PROPER FUNCTION	New	80.00	0.00
2	CARRY UP BODY CAVITY PRESERVATION FOR AFFECTED AREA \$50 PER PANEL	New	200.00	0.00
3	REPLACING ACCIDENT DAMAGES PARTS ,KNOCK ,JACK AND STRAIGHTEN ACCIDENT DAMAGES AREA	New	1,200.00	400.00
4	SPRAY PAINTING FOR ACCIDENT AFFECTED DAMAGED AREA ,INCLUDING TAILGATE IN & OUT ,BUMPER ,REAR END PANEL SIDE COVER X2 ,TOUCH UP FENDER	New	1,200.00	500.00
5	CARRY OUT WHEEL ALIGNMENT	New	120.00	0.00
6	REMOVING AND INSTALLING REAR BOOTLID COMPARTMENT GARNISH ,TRIMING ETC,TO FACILITATE THE NECESSARY REPAIR	New	150.00	30.00
7	TRANSFERRING TAILGATE BOOTLID LOCK MECHANISM TRIMING ETC TO THE NEW TAILGATE /BOOTLID	New	120.00	0.00
8	CHECKING CENTRAL LOCK SYSTEM FOR PROPER FUNCTION	New	120.00	0.00
9	REMOVING AND INSTALLING REAR FENDER INTERNAL GARNISH AND TRAINING TO FACILITATE THE NECESSARY REPAIR	New	120.00	0.00
10	REMOVING AND INSTALLING REAR WINDOW /WINDSCREEN GLASS	New	150.00	0.00
11	TO REMOVE AND INSTALL REAR CAMERA	New	80.00	0.00
12	TRANSFERRING TAILGATE AND REAR END WIRING HARNESS FOR PROPER FUNCTION	New	150.00	0.00
13	WATER TEST AFTER ACCIDENT REPAIR BODY WORK	New	120.00	0.00
14	PAINT PROTECTION COATING FOR ACCIDENT AFFECTED AREAS	New	350.00	0.00
15	CARRY OUT DIAGNOSIS CHECK INCLUDING CLEANING ACCIDENT FAULT CODE	New	150.00	0.00
Gross Labour Cost (\$\$)			4,310.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >