



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SND5761S HONDA SHUTTLE

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy / C rae	\$ 1,233.20 930
2	1 2	Bumper bracket 44 / Nec	\$ 190.00 100
3	2	bumper reflector X NN	\$ 220.00
4	1	Rear end panel Mprn X	\$ 950.00
5	1	Tailgate X Mprn	\$ 1,800.00
6	1	Tailage inner trim cover X NN	\$ 380.00
7	1	Tailgate lock X NN	\$ 320.00
8	2	Tailgate abosorber X NN	\$ 600.00
9	1	Front bumper tow cover X NN	\$ 95.00
10	1	Tailgate rubber seal X / torn	\$ 250.00 230
11	1	Top cover trim X NN	\$ 280.00
12	1	Middle chrome assy ? NN X nn	\$ 457.50
10	1	Tailgate light left X NN	\$ 850.00
11	1	Tailgate light right X NN	\$ 850.00

\$ 8,475.70 1260

20% 252
7 = 1008



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SND5761S HONDA SHUTTLE

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	10	Bumper clips / nec	\$ 50.00
2	8	Fender inner board clips X nn	\$ 40.00
3	6	Middle chrome moulding clips X nn	\$ 40.00
4	6	Top garnish clips X nn	\$ 40.00
5	8	Front support panel top garnish clips X nn	\$ 30.00
6	1	Front no plate with cashing X nn	\$ 80.00
7	1	Sensor X nn	\$ 350.00
<u>Special Nett Items</u>			\$ 630.00 50



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

Number Plate: SND5761S

Modle: HONDA SHUTTLE

No	Description	Labour Charges
1	Checking rear wiring harness and lighting system for proper function	\$ 80.00 X
2	Carry up body cavity preservation for affected area \$50 per panel	\$ 200.00 X
3	Replacing accident damages parts, knock, jack and straighten accident damages area	\$ 1,200.00 400
4	Spray painting for accident affected damaged area, including: Tailgate in & out, bumper, rear end panel side cover x2, touch up fender	\$ 1,200.00 500
5	Carry out wheel alignment	\$ 120.00 X
6	Removing and installing rear bootlid compartment garnish, trimming etc, to facilitate the necessary repair.	\$ 150.00 30
7	Transferring tailgate /bootlid lock mechanisam, trimming etc to the new tailgate /bootlid	\$ 120.00 X
8	Checking central lock system for proper function	\$ 120.00 X
9	Removing and installing rear fender internal garnish and training to facilitate the necessary repair	\$ 120.00 X
10	Removing and installing rear window /windscreen glass	\$ 150.00 X
11	To remove and install rear camera	\$ 80.00 X
12	Transferring tailgate and rear end wiring harness for proper function	\$ 150.00 X
13	Water test after accident repair body work	\$ 120.00 X
14	Paint protection coating for accident affected areas	\$ 350.00 X
15	Carry out diagnosis check including cleaning accident fault code	\$ 150.00 X
Total labour :		\$ 4,310.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

T = 1988

1r fem 4 days
9th
Part/Part