

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22008931/TNY3Q2
Date: 18/11/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSNW00130292100	
Claimant Vehicle No : SGL41K	Insured Vehicle No : GBH9032H	
Date of Loss: 07/09/2022	Nature of Claim: TP	Claim No: SNM22D206390/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGL41K		
Make & Model:	HONDA ODYSSEY, 2.4 (A)	Engine No:	K24A65005100
Reg. Date:	19/11/2008 (Man. Year: 2008)	Chassis No:	JHMRB18508C205101
Colour:	Green	Odometer:	204434 km
Engine Capacity:	2354 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,294.26	3,775.64	8,518.62	69.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,760.00	1,740.00	3,020.00	63.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,054.26	5,515.64	11,538.62	67.66
Approved Total (Overridden) (\$\$)		4,400.00		
	17,054.26	4,400.00	12,654.26	74.20
+ GST 7.00/7.00% (\$\$)	1,193.80	308.00	885.80	74.20
Nett Amount (\$\$)	18,248.06	4,708.00	13,540.06	74.20

INSPECTION

Date of Assignment:	12/09/2022	
Date Inspected:	12/09/2022	Inspected At: 56 Loyang Way, #04-04 Loyang Enterprise Building
Estimated Period of Repair:	6.0 days	Repairer: AP Automotive Services Pte Ltd

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Nov 2022)
Parts:	M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGL41K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE	Bent	1,257.90 FL	*1,030.50 FL
2	2	*TAILGATE LAMP WITH CHROME	Not Necessary	1,167.00 FL	*- FL
3	1	*TAILGATE OUTER GARNISH	Deformed	644.40 FL	*406.10 FL
4	2	*TAILGATE DAMPER	Not Necessary	310.60 FL	*- FL
5	1	*TAILGATE HINGE RH	Not Necessary	36.50 FL	*- FL
6	1	*TAILGATE LOGO	Necessary	47.60 FL	*47.60 FL
7	1	*TAILGATE EMBLEM ODYSSEY WITH CHROME	Not Necessary	232.50 FL	*- FL
8	1	*TAILGATE INNER LOCK	Bent	169.40 FL	*169.40 FL
9	1	*TAILGATE WEATHERSTRIP	Twisted	121.60 FL	*121.60 FL
10	2	*TAILGATE STOPPER	Not fitted	30.00 FL	*- FL
11	1	*TAILGATE INNER BOARD	Cracked	282.40 FL	*282.40 FL
12	1	*TAILGATE INNER TOP GARNISH	Not Necessary	92.10 FL	*- FL
13	2	*TAILGATE INNER SIDE GARNISH	Not Necessary	178.80 FL	*- FL
14	1	*TAILGATE WIPER BLADE	Missing	49.30 FL	*49.30 FL
15	1	*TAILGATE WIPER ARM	Missing	124.00 FL	*124.00 FL
16	1	*TAILGATE WIPER MOTOR	Not Necessary	393.60 FL	*- FL
17	1	*TAILGATE WIPER MOTOR HEAD COVER	Not Necessary	19.00 FL	*- FL
18	1	*TAILGATE WINDSCREEN GLASS	Not Necessary	1,400.00 FL	*- FL
19	1	*TAILGATE WINDSCREEN MOULDING	Necessary	165.60 FL	*165.60 FL
20	2	*TAILLAMP	Not Necessary	1,361.60 FL	*- FL
21	2	*TAILLAMP BRACKET	Not Necessary	87.40 FL	*- FL
22	2	*TAILLAMP BOLT COVER	Not Necessary	16.00 FL	*- FL
23	1	*TAILLAMP PANEL RH	Not Necessary	183.10 FL	*- FL
24	1	*REAR BUMPER	Deformed	734.30 FL	*583.60 FL
25	1	*REAR BUMPER REFLECTOR RH	Not Necessary	50.00 FL	*- FL
26	2	*REAR BUMPER BOLT COVER	Not Necessary	48.00 FL	*- FL
27	1	*REAR BUMPER TOW HOOK COVER	Deformed	14.10 FL	*14.10 FL
28	1	*REAR BUMPER SIDE RETAINER	O/S Not Necessary/N/S Deformed	56.00 FL	*28.00 FL
29	2	*REAR FENDER INNER COWLING	Not Necessary	210.20 FL	*- FL
30	1	*REAR FENDER INNER TRIM (UPPER)	O/S Not Necessary/N/S Deformed	540.20 FL	*270.10 FL
31	2	*REAR FENDER INNER TRIM	Not Necessary	1,285.40 FL	*- FL
32	1	*REAR END PANEL	Bent	438.00 FL	*438.00 FL
33	1	*REAR END PANEL TOP GARNISH	Cracked	216.40 FL	*216.40 FL
34	1	*REAR FLOOR PANEL	Repair	1,118.50 FL	*- FL
35	1	*REAR FLOOR PANEL COVER BOARD	Deformed	375.70 FL	*254.10 FL
36	1	*REAR NUMBER PLATE	Dented	50.00 FS	*45.00 FS
37	8	*TAILGATE OUTER GARNISH CLIP	Not Necessary	52.00 FS	*- FS
38	1	*TAILGATE INNER BOARD CLIP	Not Necessary	80.00 FS	*- FS
39	6	*TAILGATE INNER TOP GARNISH CLIP	Not Necessary	39.00 FS	*- FS
40	16	*TAILGATE INNER SIDE GARNISH CLIP	Not Necessary	104.00 FS	*- FS
41	1	*TAILGATE WINDSCREEN SEALANT	Necessary	180.00 FS	*60.00 FS
42	1	*TAILGATE WINDSCREEN INNER SEAL	Necessary	80.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

11/18/22, 9:02 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
44	18		*REAR FENDER INNER COWLING CLIP	Not Necessary	117.00 FS	*- FS
45	18		*REAR FENDER TOP TRIM (INNER) CLIP	Not Necessary	117.00 FS	*- FS
46	3		*REAR FENDER INNER TRIM CLIPS	Not Necessary	25.50 FS	*- FS
47	1		*TAILLAMP CLIP	Not Necessary	80.00 FS	*- FS
48	6		*TAILLAMP PANEL RH SEALANT	Not Necessary	39.00 FS	*- FS
49	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
50	8		*REAR END PANEL INSULATION SEAL	Necessary	52.00 FS	*40.00 FS
51	6		*REAR FLOOR PANEL INSULATOR SEAL	Not Necessary	39.00 FS	*- FS
52	16		*REAR EXHAUST CHROME PIPE RH	Not Necessary	104.00 FS	*- FS
53	1		*TRIANGLE BREAK DOWN SIGN	Not Necessary	80.00 FS	*- FS
54	4		*REVERSE SENSOR	Not Working	180.00 FS	*180.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					14,985.70	4,615.80
- List Item Discount on L Items 20.00/20.00% (\$\$)					2,691.44	840.16
Total Parts (\$\$)					12,294.26	3,775.64
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	2,000.00	700.00
2	SPRAY PAINTING ON AFFECTED AREAS	New	1,600.00	700.00
3	TO APPLY RUST PROOFING	New	240.00	40.00
4	REMOVE AND REFIT REAR WINDOW GLASS	New	220.00	120.00
5	ECU DIAGNOSTIC AND CLEARING FAULT CODES	New	180.00	0.00
6	TRANFER TAILGATE MECHANISM	New	120.00	60.00
7	REMOVE AND REFIX TAILGATE WINDSCREEN	New	160.00	120.00
8	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
9	CONDUCT 4 WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (\$\$)			4,760.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >