

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 8239H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
2	FRONT HEADLAMP @\$1784.50 (CONSISTENT)	MTG CRACKED	3,569.00	1,784.50
2	FRONT HEADLAMP TOP BRACKET @\$35.00 (CONSISTENT)	SERVICEABLE	70.00	-
2	FRONT HEADLAMP LOWER BRACKET @\$45.00 (CONSISTENT)	CRACKED	90.00	90.00
1	FRONT CENTRE GRILLE BASE (CONSISTENT)	CRACKED	495.00	381.50
1	FRONT CENTRE GRILLE OUTER GARNISH (CONSISTENT)	CRACKED	380.00	342.60
1	FRONT CENTRE GRILLE LOWER CHROME (CONSISTENT)	DENTED	175.00	175.00
1	FRONT CENTRE GRILLE 'HONDA' LOGO (CONSISTENT)	NECESSARY	37.40	37.40
1	FRONT BUMPER (CONSISTENT)	BUCKLED	951.70	762.70
10	FRONT BUMPER CLIP @\$5.00(CONSISTENT)	NECESSARY	50.00	50.00
2	FRONT BUMPER SIDE RETAINER @\$25.60(CONSISTENT)	N/S DISTORTED	51.20	25.60
1	FRONT BUMPER RH FOG LAMP COVER (CONSISTENT)	SERVICEABLE	82.60	-
1	FRONT BUMPER LOWER LID (CONSISTENT)	SERVICEABLE	450.30	-
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	SERVICEABLE	280.50	-
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	BENT	368.80	321.00
1	FRONT SUPPORT PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	681.20	-
1	FRONT AIR-CON CONDENSOR(CONSISTENT)	SERVICEABLE	950.20	-
	LESS 20% DISCOUNT		-1,736.58	-794.06
			6,946.32	3,176.24
	<u>LABOUR</u>			
	WIRING.		120.00	20.00
	TUFFKOTE.	NOT NECESSARY	100.00	-
	SPRAY PAINTING.		1,000.00	400.00
	LABOUR CHARGES .		1,000.00	400.00
			2,220.00	820.00
	GRAND TOTAL		9,166.32	3,996.24

Report Ref No. CC4/ASM22008936/Kpa3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,200.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM22008936/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser