

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Page No.:1 of 1

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22008937/Rqy3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 13/10/2022 SINGAPORE 068811 ATTN: HO WINNIE Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHC 1521X SJM 7435X Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S2M04ARY Excess (\$) 0.00 HO WINNIE 12/09/2022 Assign From Assign Date **Vehicle Particulars & Condition** 2. MERCEDES BENZ C180K Make & Model 1796 c.c HIDDEN 2009 Engine No. Year of Reg. WDD2040462A203742 Chassis No. Colour GREY 227732 KM Odometer Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 225/45 R17 **GOODYEAR** 6 mm L/H Front Tyre 225/45 R17 **GOODYEAR** 6 mm 225/45 R17 GOODYEAR R/H Rear Tyre 6 mm L/H Rear Tyre 225/45 R17 **GOODYEAR** 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 09/09/2022 Inspect Date / Time 15/09/2022 (02:05 PM) Accident Date SZE KANG AUTOMOBILE SPRAYING SERVICES Survey held at BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #03-17 AMK AUTO POINT SINGAPORE 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

Report Ref No. CS3/ASM22008937/Rgy3e2

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

Estimate Days of Repair

Inspected By

Automotive Assessor

5b.

MOHAMMED RASUL BIN MOHD YUNUS

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

ESTIMATED NORMAL PERIOD FOR REPAIR:

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

K.K.LAU CPT(RET)

DECD Astro Consultant CAE Library of August

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

3 Working Days