



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)			Ref:	CS/SPF22008938/Any3e2
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1			Date:	07/11/2022
HEMMANT ROADSINGAPORE 438675				
ATTN: HAFIZUL FARHAN			Code:	SPF
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	QX 1485A	Veh. Inspected	SJM 301U	
Policy No.		Coverage (\$)	0.00	
Claim No.	ACS/105/009/2022/055	Excess (\$)	0.00	
Assign From	HAFIZUL FARHAN	Assign Date	12/09/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA HARRIER	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTEKB3GH00J002398	Colour	BLACK	
Odometer	89091 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	235/55 R18	MICHELIN	6 mm	
L/H Front Tyre	235/55 R18	MICHELIN	6 mm	
R/H Rear Tyre	235/55 R18	MICHELIN	6 mm	
L/H Rear Tyre	235/55 R18	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	10/09/2022	Inspection Date	12/09/2022	
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>4 Working Days</b>	