

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008941/EPA3Q2**Date:** 27/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220068255
Claimant Vehicle No :	FBT8148B	Insured Vehicle No :	SJR6820Y
Date of Loss:	02/09/2022	Nature of Claim:	TP
		Claim No:	3729487545SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBT8148B	Engine No:	KCE1E1002592
Make & Model:	HONDA CB150X, 149cc	Chassis No:	MH1KCE114NK002604
Reg. Date:	07/06/2022 (Man. Year: 2022)	Odometer:	3593 km
Colour:	Red		
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	100/80-17	Rear Tyre Size:	140/70-17
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,785.00	2,407.50	377.50	13.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	480.00	360.00	120.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	3,265.00	2,767.50	497.50	15.24
+ Loss of Use (3.0 x S\$25.00/day) (S\$)		75.00		
Nett Liability (S\$)		2,842.50		

INSPECTION

Date of Assignment:	09/09/2022	
Date Inspected:	09/09/2022	Inspected At: Pang Scooter Service (HQ) BLK 1006 BUKIT MERAH LANE 2 #01-06 Singapore 159762
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLER BAR	Bent	195.00 F	*195.00 FL
2	1		*UNDER BRACKET	Bent	298.00 F	*298.00 FL
3	1		*SET STEERING CON	Necessary	120.00 F	*120.00 FL
4	1		*BRAKE LEVER	Bent	45.00 F	*45.00 FL
5	1		*R/H HANDLER END	Cut	48.00 F	*48.00 FL
6	1		*R/H MIRROR	Broken	45.00 F	*45.00 FL
7	1		*VISOR	Broken	195.00 F	*195.00 FL
8	4		*VISOR RUBBER BUSH	Necessary	80.00 F	*80.00 FL
9	1		*R/H FOOT REST BRACKET	Bent	165.00 F	*165.00 FL
10	1		*R/H FRONT FOOT REST	Bent	85.00 F	*85.00 FL
11	1		*BRAKE PEDAL	Bent	90.00 F	*90.00 FL
12	1		*MUFFLER ASSY	Bent	780.00 F	*700.00 FL
13	1		*MUFFLER GUARD	Cut	98.00 F	*98.00 FL
14	1		*MUFFLER JOINT GASKET	Necessary	25.00 F	*25.00 FL
15	1		*FAIRING STAY	Bent	198.00 F	*198.00 FL
16	1		*RADIATOR ASSY	Bent	268.00 F	*268.00 FL
17	1		*COOLANT	Necessary	50.00 F	*20.00 FL
					Sub Total (S\$)	2,785.00 2,675.00
					- List Item Discount on L Items 0.00/10.00% (S\$)	0.00 267.50
					Total Parts (S\$)	2,785.00 2,407.50

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TSP (TOWING)	New	80.00	60.00
2	LABOUR	New	400.00	300.00
Gross Labour Cost (\$\$)			480.00	360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >