

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

NOT Authorized
 L1 Rep @ 19,400/hr
 Recovery After Pain

21 days

REPAIR ESTIMATE GZ2181C

No.	Qty	List Items			
1	1	Front bumper	\$ Bu	663.90	✓
2	1	Font bumper LH fog lamp cover	\$ In	226.90	X
3	2	Front bumper side retainer	MSD11 \$	60.60	✓
4	1	LH headlamp	\$ Bu	730.50	X
5	1	Front grille	\$ CM	519.30	✓
6	1	Front grille centre "TOYOTA" logo	\$ In	79.10	✓
7	1	Front LH fender	\$ Bu	1,288.90	✓
8	1	Front LH fender signal lamp	\$ In	22.90	X
9	1	Front LH fender under shield	D11 \$	256.90	✓
10	1 set	Front LH mudflap (C/w 1 set)	\$ D11	147.80	✓
11	1 set	Front fender under shield clips	\$ In	40.00	✓
12	1	Front LH shock absorber	\$ Bu	361.00	✓
13	1	Front LH lower arm 1207.40	\$ Bu	1,414.70	✓
14	1	Front LH top arm	\$ Bu	1,001.30	✓
15	1	Front LH knuckle arm	\$ Bu	1,120.50	✓
16	1	Front LH wheel hub	\$ Bu	417.20	✓
17	1	Front LH wheel bearing	\$ In	189.30	✓
18	1	Steering rack & pinion 4220.60	Bu/In	4,926.70	✓
19	1	Front engine cross member	\$ Bu	2,997.50	X
20	1	Front LH door mirror assy	\$ Bu/In	950.00	✓
21	1	Front LH door 1457	\$ Bu	1,786.40	✓
22	1	Front LH door "HILUX" emblem	\$ In	47.93	✓
23	1	Front LH door "D4D" emblem	\$ In	60.60	✓
24	1	Front LH door outer handle	\$ In	235.30	✓
25	2	Front LH door hinge (Top & bottom)	Lower \$ Bu	373.80	✓
26	1	Front LH door weatherstrip	\$ In	275.65	X
27	1	Rear bumper	\$ Bu	699.75	✓
28	1	Rear bumper inner reinforcement	\$ Bu	486.70	✓
29	2	Rear bumper inner bracket	\$ In	370.00	X
30	2	Rear number plate lamp	\$ CM	85.70	✓
31	1	Rear tow hook	\$ In	187.40	X
32	1	Rear tailgate	\$ Bu	1,517.90	✓
33	1	Rear tailgate LH "TOYOTA" emblem	\$ In	67.80	✓
34	1	Rear tailgate RH "HILUX" emblem	\$ In	56.93	✓
35	1	Rear tailgate RH "J" emblem	\$ In	49.80	✓
36	2	Rear tailgate top side lock	\$ Bu	355.60	✓
37	2	Taillamp	\$ Bu	739.40	✓
38	2	Rear side body panel (Fender) @ 1801.20	\$ Bu	3,956.80	✓
39	1	Rear floor deck assy	\$ Bu	2,504.70	✓
40	1	Rear deck end panel	\$ Bu	789.63	✓
			\$	32,062.79	
			Less 25%	\$ 8,015.70	
			Total :	\$ 24,047.09	

Special Nett Items

41	1	Front number plate	\$	Rn	45.00	201n
42	1	Front LH wheel rim	\$	Rn	220.00	✓
43	1	Front LH tyre	\$	Tn	180.00	208n 365n
44	1	Front LH door lower black sticker	\$	Rn	40.00	✓
45	1 set	Reverse sensors	\$	Net	250.00	2001n
46	1	Rear number plate	\$	Net	45.00	201n
47	1	Rear tailgate LH "70km/h" sticker	\$	Rn	12.00	—
48	1	Rear tailgate RH "8pax" sticker	\$	Rn	12.00	—
			Total :	\$	804.00	

Labour

1	Towing charges.	\$	100.00	50
2	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$	2,500.00	2200
3	To putty and spray Spray Paintings charges.	\$	2,400.00	1800
4	To check wirings and lightings for front & rear portion.	\$	60.00	40
5	To remove, refir front undeer carriages.	\$	300.00	200
6	To conduct computerise wheel alignment test.	\$	80.00	60
7	To remove, refit front LH door fittings.	\$	80.00	60
8	To lift up & dismantle rear deck assy.	\$	300.00	200
9	To supply & apply anti rust treatments.	\$	120.00	✓
			Total :	\$ 5,940.00

Total Parts and Labour : \$ 30,791.09

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: