

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III22008945/TYA3Q2**Date:** 07/06/2023**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0009917
<b>Claimant Vehicle No :</b>	SHD3560P	<b>Insured Vehicle No :</b>	SMP147Y
Date of Loss:	07/09/2022	Nature of Claim:	TP
		Claim No:	MFL2022D0004937

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHD3560P</b>	Engine No:	2ZRR923714
Make & Model:	TOYOTA PRIUS, 1.5 HYBRID (A)	Chassis No:	JTDKB3FU003530448
Reg. Date:	20/09/2016 (Man. Year: 2016)	Odometer:	710060 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,878.16	3,632.18	1,245.98	25.54
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,820.00	880.00	940.00	51.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,709.16</b>	<b>4,523.18</b>	<b>2,185.98</b>	<b>32.58</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,600.00</b>		
<b>(S\$)</b>	6,709.16	3,600.00	3,109.16	46.34
<b>+ GST 7.00/7.00% (S\$)</b>	469.64	252.00	217.64	46.34
<b>Nett Amount (S\$)</b>	<b>7,178.80</b>	<b>3,852.00</b>	<b>3,326.80</b>	<b>46.34</b>
<b>+ Loss of Use (4.0 x S\$40.00/day) (S\$)</b>		160.00		
<b>+ Car Rental (4.0 x S\$125.40/day) (S\$)</b>		501.60		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>4,521.05</b>		

**INSPECTION**

Date of Assignment:	08/09/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	08/09/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang)
			59 Loyang Drive
			Singapore 508969
Estimated Period of Repair:	2.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Ezlyna

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 22 Nov 2022)
<b>Parts:</b> 144	TOYOTA PRIUS 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHD3560P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FOG LAMP	Cracked	920.00 FL	*920.00 FL
2	1		*HEADLAMP RH	Cracked	2,637.60 FL	*2,637.60 FL
3	1		*FRONT BUMPER COVER	Torn	586.18 FL	*586.18 FL
4	1		*FRONT BUMPER SIDE BRACKET RH	Not Necessary	90.75 FL	*- FL
5	1		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
6	1		*FRT FENDER HYBRID EMBLEM RH	Necessary	86.50 FL	*86.50 FL
7	1		*FRT FENDER SHIELD RH	Deformed	198.50 FL	*198.50 FL
8	1		*FRONT BUMPER SIDE RETAINER RH	Deformed	77.00 FL	*77.00 FL
9	1		*FRT WHEEL RIM RH	Not Necessary	1,570.55 FL	*- FL
10	1		*WIPER SPARE TANK	Deformed	181.80 FL	*181.80 FL
11	1		*RENEW FRT ADVERTISEMENT RH	Cut	100.00 F	*100.00 F

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,470.88</b>	<b>4,809.58</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,592.72	1,177.40
<b>Total Parts (\$\$)</b>	<b>4,878.16</b>	<b>3,632.18</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,100.00	350.00
2	SPRAY PAINTING CHARGE	New	600.00	500.00
3	TUFF KOTE	New	60.00	0.00
4	CHECK ALL LIGHTING	New	60.00	30.00
Gross Labour Cost (\$\$)			1,820.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >