

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22008953/GVY3M4**Date:** 09/02/2023**REFERENCE**

|                              |                                               |                             |                    |           |                          |
|------------------------------|-----------------------------------------------|-----------------------------|--------------------|-----------|--------------------------|
| Handling Insurer:            | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:                  | DMPCSNW00101222101 |           |                          |
| <b>Claimant Vehicle No :</b> | FBQ9850R                                      | <b>Insured Vehicle No :</b> | SKU1638M           |           |                          |
| Date of Loss:                | 18/06/2022                                    | Nature of Claim:            | TP                 | Claim No: | SNM22D204334/C02/KHONGLH |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>FBQ9850R</b>                   |             |                   |
| Make & Model:               | YAMAHA AEROX GDR155R, 155cc CVT   | Engine No:  | G3J1E0397540      |
| Reg. Date:                  | 22/01/2020 (Man. Year: 2019)      | Chassis No: | MH3SG4620KJ066505 |
| Colour:                     | White                             | Odometer:   | 0 km              |
| Engine Capacity:            | 155 cc                            |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |            |                  |            |
|-------------------|------------|------------------|------------|
| Front Tyre Size:  | 110/80-14  | Rear Tyre Size:  | 150/70-14  |
| Front Left Side:  | MITAS 5 mm | Rear Left Side:  | MITAS 5 mm |
| Front Right Side: | 0 mm       | Rear Right Side: | 0 mm       |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 5,885.00          | 4,162.50          | 1,722.50          | 29.27         |
| Miscellaneous Items           | 0.00              | 0.00              | 0.00              |               |
| Labour                        | 1,330.00          | 450.00            | 880.00            | 66.17         |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>7,215.00</b>   | <b>4,612.50</b>   | <b>2,602.50</b>   | <b>36.07</b>  |
| <b>+ GST 8.00/8.00% (S\$)</b> | 577.20            | 369.00            | 208.20            | 36.07         |
| <b>Nett Amount (S\$)</b>      | <b>7,792.20</b>   | <b>4,981.50</b>   | <b>2,810.70</b>   | <b>36.07</b>  |

**INSPECTION**

|                             |            |               |                                                                       |
|-----------------------------|------------|---------------|-----------------------------------------------------------------------|
| Date of Assignment:         | 12/09/2022 |               |                                                                       |
| Date Inspected:             | 13/09/2022 | Inspected At: | KIVILE ENTERPRISE<br>BLK 3007 #01-408<br>UBI ROAD 1, SINGAPORE 408701 |
| Estimated Period of Repair: | 5.0 days   |               |                                                                       |

**Adjuster:** XING GUO QIANG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,914.00 NETT)

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                  |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------|
| <b>Part Source:</b>  | (Last Synchronised: 08 Feb 2023)                                                                                                                                             |                                                                  |
| <b>Parts:</b>        | N/A                                                                                                                                                                          | YAMAHA AEROX GDR155R 155cc CVT (Model not available in database) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for FBQ9850R)                                                                                                                                    |                                                                  |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                  |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                  |

### Recommended Parts

| No. | Qty | Part No. | Particulars            | Condition | Repairer's | Amount     |
|-----|-----|----------|------------------------|-----------|------------|------------|
| 1   | 1   |          | *SET COVER             | Distorted | 480.00 F   | *480.00 FL |
| 2   | 1   |          | *HANDLE BAR            | Bent      | 60.00 F    | *60.00 FL  |
| 3   | 1   |          | *BALANCE               | Cut       | 50.00 F    | *50.00 FL  |
| 4   | 1   |          | *BRAKE LEVER RH        | Cut       | 25.00 F    | *25.00 FL  |
| 5   | 1   |          | *BRAKE PUMP            | Cut       | 180.00 F   | *180.00 FL |
| 6   | 1   |          | *HEADLIGHT             | Cracked   | 450.00 F   | *450.00 FL |
| 7   | 1   |          | *LAMP STAY             | * Check   | 160.00 F   | *- FL      |
| 8   | 1   |          | *FORK                  | * Check   | 360.00 F   | *- FL      |
| 9   | 1   |          | *FORK LOWER CAM        | * Check   | 180.00 F   | *- FL      |
| 10  | 1   |          | *MUDGUARD GARNISH      | Cut       | 45.00 F    | *45.00 FL  |
| 11  | 1   |          | *KEY COVER GARNISH     | Cracked   | 85.00 F    | *85.00 FL  |
| 12  | 1   |          | *TANK GARNISH          | Missing   | 85.00 F    | *85.00 FL  |
| 13  | 1   |          | *TANK                  | Bent      | 280.00 F   | *280.00 FL |
| 14  | 1   |          | *DICOM PUMP            | Damaged   | 360.00 F   | *360.00 FL |
| 15  | 2   |          | *SIDE FAIRING GARNISH  | Cut       | 120.00 F   | *120.00 FL |
| 16  | 1   |          | *FOOT PEDAL            | Cracked   | 85.00 F    | *85.00 FL  |
| 17  | 1   |          | *LOWER SIDE GARNISH RH | Deformed  | 45.00 F    | *45.00 FL  |
| 18  | 1   |          | *RADIATOR              | Cut       | 250.00 F   | *250.00 FL |
| 19  | 1   |          | *RADIATOR COVER        | Cut       | 35.00 F    | *35.00 FL  |
| 20  | 1   |          | *EXHAUST PIPE          | Bent      | 480.00 F   | *480.00 FL |
| 21  | 1   |          | *EXHAUST PIPE COVER    | Cracked   | 65.00 F    | *65.00 FL  |
| 22  | 1   |          | *EXHAUST HOLDER        | Broken    | 180.00 F   | *180.00 FL |
| 23  | 1   |          | *REAR ABSORBER         | Bent      | 280.00 F   | *280.00 FL |
| 24  | 1   |          | *REAR BOX              | Missing   | 145.00 F   | *145.00 FL |
| 25  | 1   |          | *REAR CARRIER          | Cut       | 145.00 F   | *145.00 FL |
| 26  | 1   |          | *SEAT                  | Cut       | 220.00 F   | *220.00 FL |
| 27  | 1   |          | *SIDE COVER GARNISH    | Cracked   | 65.00 F    | *65.00 FL  |
| 28  | 1   |          | *MIRROR                | Distorted | 40.00 F    | *40.00 FL  |
| 29  | 1   |          | *MIRROR HOLDER         | Bent      | 25.00 F    | *25.00 FL  |
| 30  | 1   |          | *REAR RIM              | * Check   | 380.00 F   | *- FL      |
| 31  | 1   |          | *REAR RIM SHIFT        | * Check   | 180.00 F   | *- FL      |
| 32  | 1   |          | *SEAT COMPARTMENT      | Cracked   | 180.00 F   | *180.00 FL |
| 33  | 1   |          | *IU                    | Cut       | 165.00 F   | *165.00 FL |

F=Franchise part. L=ListItemDisc.

|                                                           |                 |                 |
|-----------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                   | <b>5,885.00</b> | <b>4,625.00</b> |
| <b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b> | 0.00            | 462.50          |
| <b>Total Parts (\$\$)</b>                                 | <b>5,885.00</b> | <b>4,162.50</b> |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                             | Particulars                            | Lab.Type | Repairer's      | Amount        |
|--------------------------------|----------------------------------------|----------|-----------------|---------------|
| <b>Labour Items</b>            |                                        |          |                 |               |
| 1                              | <b>BODY FRAME REPAIR</b><br>(* Check)  | New      | 500.00          | 0.00          |
| 2                              | <b>BODY FRAME RESPRAY</b><br>(* Check) | New      | 280.00          | 0.00          |
| 3                              | <b>LABOUR</b>                          | New      | 500.00          | 400.00        |
| 4                              | <b>TOWING</b>                          | New      | 50.00           | 50.00         |
| <b>Gross Labour Cost (S\$)</b> |                                        |          | <b>1,330.00</b> | <b>450.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >