



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2207353

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 29/11/2022
Reference CC4/LPC22008956/Upa3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SKV 8197S
Insured Veh. GBD 174L
Claim No. 22/22/22/VC05/026261
Policy No.
Accident Date 05/09/2022
Inspection Date 12/09/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC22008956/Upa3q2 Date: 29/11/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 174L		Veh. Inspected	SKV 8197S
Policy No.			Coverage (\$)	0.00
Claim No.	22/22/22/VC05/026261		Excess (\$)	0.00
Assign From	GERALD		Assign Date	09/09/2022
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ GLA180 (A)		c.c	1595
Engine No.	HIDDEN		Year of Reg.	2018
Chassis No.	WDC1569422J535469		Colour	BLACK
Odometer	162411 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50 R18	BRIDGESTONE	7 mm	
L/H Front Tyre	235/50 R18	BRIDGESTONE	7 mm	
R/H Rear Tyre	235/50 R18	BRIDGESTONE	7 mm	
L/H Rear Tyre	235/50 R18	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/09/2022		Inspection Date	12/09/2022
Survey held at	2ND AUTO PTE LTD 15 KAKI BUKIT ROAD 4, #01-53, BARTLEY BIZ CENTRE, SINGAPORE 417808			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 8197S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TOP BUMPER ASSY	DISTORTED / TORN	1,450.00	1,266.32
1	REAR BUMPER TOW COVER }		98.00	-
1	REAR CENTRE BUMPER ASSY	DEFORMED	1,155.00	755.20
1	REAR BUMPER LOWER SPOILER ASSY	CRACKED	1,256.00	957.25
1	REAR BUMPER TOP CHROME MOULDING	NECESSARY	297.00	297.00
2	REAR BUMPER SIDE RETAINER	NOT NECESSARY	122.00	-
2	REAR BUMPER BRACKET	O/S CRACKED	123.00	60.00
1	REAR BUMPER REINFORCEMENT	BENT	497.00	497.00
1	REAR BUMPER INNER BEAM	NOT NECESSARY	289.00	-
1	REAR EXHAUST CHROME O/S	DAMAGED	266.00	266.00
1	REAR TAILGATE ASSY	TO REPAIR SEE LABOUR	1,693.00	-
1	REAR TAILGATE CENTRE LOGO	NOT NECESSARY	126.00	-
1	REAR TAILGATE '180' EMBLEM	NOT NECESSARY	105.00	-
1	REAR TAILGATE 'GLA' EMBLEM	NOT NECESSARY	102.00	-
1	REAR TAILGATE 'CYCLE AND CARRIAGE' EMBLEM	NOT NECESSARY	106.00	-
1	REAR TAILGATE LOCK MECHANISM	NOT NECESSARY	282.00	-
1	REAR TAILGATE LOCK CATCH	NOT NECESSARY	96.00	-
1	REAR TAILGATE CHROME MOULDING	NOT NECESSARY	289.00	-
1	REAR TAILGATE WEATHERSTRIP	NOT NECESSARY	288.00	-
1	REAR TAILGATE INNER TRIM GARNISH	NOT NECESSARY	387.00	-
2	REAR NO PLATE LAMP	NOT NECESSARY	128.00	-
1	REAR RIGHT TAILLAMP	NOT NECESSARY	875.00	-
1	REAR TAILGATE RIGHT TAILLAMP	NOT NECESSARY	793.00	-
1	REAR RIGHT FENDER OUTER GARNISH	DISTORTED	475.00	475.00
1	REAR END LOWER PANEL	TO REPAIR SEE LABOUR	1,284.00	-
1	REAR EXHAUST HEAT SHIELD	BENT	193.00	193.00
	LESS 10% DISCOUNT		-1,277.50	-476.68
			11,497.50	4,290.09

Report Ref No. CC4/LPC22008956/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	160.00	60.00
1	REAR BUMPER LOWER SPOILER SEALANT (SN)	NOT NECESSARY	100.00	-
1	SET REAR BUMPER LOWER SPOILER CLIPS (SN)	NOT NECESSARY	80.00	-
8	REAR TAILGATE INNER TRIM GARNISH CLIPS (SN)	NOT NECESSARY	40.00	-
4	REAR TAILGATE OUTER CHROME MOULDING CLIPS (SN)	NOT NECESSARY	30.00	-
8	REAR RIGHT FENDER INNER GARNISH CLIPS (SN)	NOT NECESSARY	50.00	-
1	REAR VIEW CAMERA (SN)	NOT NECESSARY	450.00	-
4	REAR BUMPER REVERSE SENSOR (SN)	O/S SHORTED (1 PCS ONLY)	1,200.00	198.00
1	REAR NO PLATE WITH GARNISH (SN)	NOT NECESSARY	100.00	-
1	REAR END LOWER PANEL SEALANT (SN)	NOT NECESSARY	140.00	-
4	REAR END LOWER PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
			2,380.00	258.00
	<u>LABOUR</u>			
	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR TAILGATE ASSY AND REAR END LOWER PANEL .		1,200.00	500.00
	TO PUTTY AND SPRAY PAINTING REAR PORTION .		1,200.00	800.00
	TO CHECK REAR LIGHTING AND WIRING .		50.00	30.00
	TO REMOVE AND INSTALL REAR BOOTLID LOCK MECHANISM .	NOT NECESSARY	80.00	-
	TO REMOVE AND INSTALL REAR EXHAUST FLANGE.	NOT NECESSARY	80.00	-
	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR.		140.00	80.00
	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA .	NOT NECESSARY	140.00	-
	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR .		80.00	50.00
	TO REMOVE & INSTALL REAR VIEW CAMERA.	NOT NECESSARY	80.00	-
	TOWING SERVICE.	NOT NECESSARY	100.00	-
			3,150.00	1,460.00
	GRAND TOTAL		17,027.50	6,008.09

Report Ref No. CC4/LPC22008956/Upa3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,800.00
---	--	--	----------

Report Ref No. CC4/LPC22008956/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKV 8197S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKV 8197S

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKV 8197S

RE-INSPECTION

