

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMW 8726L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT LID	NOT NECESSARY	1,365.90	-
1	REAR BOOT LOGO	NOT NECESSARY	79.00	-
1	REAR BUMPER	DENTED / DEFORMED	1,271.35	1,261.32
1	REAR BUMPER TOWING COVER	SERVICEABLE	53.20	-
2	REAR BUMPER NUMBER PLATE LAMP @\$62.30	NOT NECESSARY	124.60	-
4	REAR BUMPER PDC SENSOR @\$359.00	SHORTED (1 PCS ONLY)	1,436.00	205.00
1	REAR EXHAUST INSULATOR	BENT	176.50	176.50
1	REAR BUMPER REINFORCEMENT	BENT	685.00	481.00
2	REAR BUMPER REINFORCEMENT STAYS @\$170.00	NOT NECESSARY	340.00	-
1	REAR BUMPER INNER FRAME GARNISH	CRACKED	289.00	182.00
2	REAR BUMPER SIDE HOLDERS @\$139.30	NOT NECESSARY	278.00	-
2	REAR TAILLAMP @\$631.70	NOT NECESSARY	1,263.40	-
	LESS 5% DISCOUNT		-368.10	-115.29
			6,993.85	2,190.53
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIP (SN)	NECESSARY	60.00	50.00
1	REAR NUMBER PLATE WITH HOLDER (SN)	SCRATCHED	50.00	40.00
			110.00	90.00
	<u>LABOUR</u>			
	PANEL BEATING.		1,000.00	400.00
	TO RESPRAY PAINTING ON AFFECTED AREAS .		800.00	500.00
	TO APPLY UNDERCOATING.	NOT NECESSARY	100.00	-
	TO REMOVE AND REFIT REAR REVERSE SENSOR .		100.00	50.00
	TO REMOVE ,REPLACE DAMAGED LAMP AND CHECK REAR WIRING .		100.00	20.00
			2,100.00	970.00
	GRAND TOTAL		9,203.85	3,250.53

Report Ref No. CS/SMO22008957/Uqy3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,600.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/SMO22008957/Uqy3q2

CHUA KANG SENG
Licensed Appraiser