

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI22008963/TWY3Q2**Date:** 09/11/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MS012459
<b>Claimant Vehicle No :</b>	SH6363X	<b>Insured Vehicle No :</b>	SLV4465H
Date of Loss:	10/09/2022	Nature of Claim:	TP
		Claim No:	M2204974

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SH6363X</b>	Engine No:	G4LEKU298718
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU164975
Reg. Date:	06/08/2019 (Man. Year: 2019)	Odometer:	319349 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,984.60	1,276.12	708.48	35.70
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	750.00	630.00	120.00	16.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,745.60</b>	<b>1,917.12</b>	<b>828.48</b>	<b>30.17</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,550.00</b>		
<b>(S\$)</b>	2,745.60	1,550.00	1,195.60	43.55
<b>+ GST 7.00/7.00% (S\$)</b>	192.19	108.50	83.69	43.55
<b>Nett Amount (S\$)</b>	<b>2,937.79</b>	<b>1,658.50</b>	<b>1,279.29</b>	<b>43.55</b>

INSPECTION

Date of Assignment:	12/09/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	12/09/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 09 Nov 2022)

**Parts:** 192      HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SH6363X)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Deformed	459.40 FL	*459.40 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING	Deformed	451.25 FL	*451.25 FL
4	1		*REAR BUMPER TOW COVER	Not Necessary	98.80 FL	*- FL
5	1		*REAR BUMPER LOWER CENTRE COVER	Not Necessary	225.00 FL	*- FL
6	1		*FOG LAMP REAR	Not Necessary	201.50 FL	*- FL
7	1		*ANTENNA SMARTKEY	Not Necessary	40.50 FL	*- FL
8	1		*REAR NUMBER PLATE WITH CASING	Cracked	50.00 F	*50.00 F
9	1		*REAR BUMPER BEAM	Not Necessary	394.80 FL	*- FL
10	1		*ADVERTISEMENT LOGO - BUMPER	Necessary	100.00 FL	*100.00 F
11	1		*ADVERTISEMENT LOGO - FENDER	Necessary	200.00 FL	*200.00 F
12	1		*REVERSE SENSOR	Not Working	180.00 F	*180.00 F

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,423.25</b>	<b>1,462.65</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	438.65	186.53
<b>Total Parts (\$\$)</b>	<b>1,984.60</b>	<b>1,276.12</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT	New	300.00	250.00
3	REMOVE / REFIX REVERSE SENSOR	New	50.00	30.00
Gross Labour Cost (\$\$)			750.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >