

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s Kok Tong Transport & Engineering

of

Insured:

Policy No.


Claims No.

Sum Insured: Excess: TBA

(Client's Record)

Make of Veh:

(Policy Condition)

 Remark: The veh had commenced its
repair at the time of inspection.
Bal. or Market Value: \$175k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: XE6780GYr Regn: 12 Oct/2021Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /☒ Truck Trailer orMake: MITSUBISHI FUSO c.c. 10677
FV70HJD2VDEAColour: White A/C: Insured / Std / NI / NASp. Reading: — T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: FV70HJA10075Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim orTyre Size: F: 295/80R22.5R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or SAILUN

Front

Rear

R/Bal. 6 mm R/Bal. 6/6 mmL/Bal. 6 mm L/Bal. 6/6 mmD.O.A. D.O.I. 12-09-2022Survey held at W/S 5PMDes. of Damages: ☒ Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : W/Weekend (\$

S + RS. SI

Photos

Other:

TOTAL

Report Filed:

Long Cond / MPB: