

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damage part(s) during resurvey
- Parts provided subject to confirmation
- Third parties' claims without prejudice* basis
- No liability for consequential damage
- Supply of parts is subject to resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: Attention: Motor Claim Department

Vfix Auto Pte Ltd

24 Chia Ping Road

Singapore 619977

Email: contact@vfixauto.com.sg

Tel: 64552957 Fax: 65628669

UEN / GST REG No.: 201830761R

ESTIMATE

DATE

8/9/2022

SHEET NO. 1 OF 1 SHEET

RE: VEHICLE NO. XE6780G MIT FUSO FP51 EURO 6			
S/NO.	QTY	DESCRIPTION	AMOUNT \$
1	1	FRONT WINDSCREEN	2,158.00
2	1	FRONT WINDSCREEN MOULDING	485.00
3	1	FRONT WIPER ARM LH	489.00
4	1	FRONT WIPER BLADE LH	35.00
5	1	FRONT WIPER MOTOR	895.00
6	1	FRONT WIPER PANEL	1,358.00
7	1	FRONT BONNET	1,920.00
8	2	FRONT BONNET ABSORBER LH RH	389.00 778.00
9	1	FRONT BONNET HANDLER LH	735.00
10	1	FRONT BONNET HINGE LH	522.00
11	1	FRONT CENTER GRILLE BLACK	1,058.00
12	1	FRONT EMBLEM - MITSUBISHI	355.00
13	1	FRONT EMBLEM - SUPER GREAT	285.00
14	1	FRONT CENTER GRILLE GRANISH	389.00
15	1	CORNEL PANEL COVER LH	685.00
16	1	CORNEL PANEL COVER RUBBER LH	215.00
17	1	CORNEL PANEL COVER UPPER GARNISH LH	458.00
18	1	SIDE MIRROR UPPER ARM LH	648.00
19	1	SIDE MIRROR MAIN ARM LH	895.00
20	2	SIDE UPPER BRACKET LH	415.00
21	1	SIDE MIRROR LOWER BRACKET LH	385.00
22	1	SIDE MIRROR UPPER MIRROR	35.00
23	1	SIDE MIRROR CENTER MIRROR	32.00
24	1	SIDE MIRROR LOWER MIRROR	38.00
25	1	FRONT HEADLAMP COVER LH	856.00
26	1	FRONT HEADLAMP LH ASSY	1,985.00
27	1	FRONT HEADLAMP BRACKET LH	385.00
28	1	FRONT FOG LAMP LH LOWER	1,152.00
29	1	FRONT BUMPER ASSY	1,859.00
30	1	FRONT BUMPER SIDE COVER LH	215.00
31	1	FOOT STEP LOWER GARNISH LH	458.00
32	1	FOOT STEP LOWER STEEL PLATE LH	289.00
33	1	FOOT STEP REFLECTOR LH	315.00
34	1	FRONT DOOR LH	1,600.00
35	1	FRONT DOOR LH UPPER HINGE	315.00
36	1	FRONT DOOR LH LOWER HINGE	325.00
37	1	FRONT DOOR CHECKER	285.00
38	1	FRONT DOOR SIGNAL LAMP	315.00
39	1	FRONT DOOR LOCK LH	385.00
40	1	FRONT DOOR HANDLER LH	785.00
41	1	FRONT DOOR HANDLER KEY LOCK	685.00
42	1	FRONT DOOR OUTER MOULDING LH	789.00
43	1	FRONT DOOR OUTER INNER MOULDING LH	712.00
44	1	FRONT DOOR TRIM LH	1,368.00
45	1	FRONT MUDGUARD PANEL LH	2,150.00
46	1	FRONT MUDGUARD PANE GARNISH LH	815.00
47	1	FRONT MUDGUARD PANE MOULDING LH	785.00
48	1	FRONT PILLAR OUTER	958.00
49	1	FRONT PILLAR INNER	895.00
50	1	FLOOR PANEL	1,223.00
51	1	AC BLOWER MOTOR	895.00
52	1	AC EVAPORATOR	1,895.00
53	1	DASHBAORD ASSY	3,856.00

S/NO.	QTY	LABOUR & MISCELLANEOUS :	AMOUNT \$
1	1	BODY SEALANT	60.00
2	1	FRONT HEADLAMP RH LIGHT BULB H11	35.00

S/NO	QTY	LABOUR & MISCELLANEOUS :	AMOUNT S\$	
1	1	To remove damaged body parts with all necessary components/ attachment apply hot-works where necessary straighten front floor panel repair, reshape body dented panel in accordance to factory specifications replace new parts refit and align into position refit all necessary components/attachments	4,500.00	2000
2	1	To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials	3,500.00	1000
3	1	Wiring and bulb checking	150.00	30
4	1	Towing Fees	150.00	X NN
5	1	To remove and replace dashboard and inter wiring	300.00	?

WENG SHENG

KOH WENG SHENG

NAME, SIGNATURE, DATE SIGNED

Lump sum repair
After repair photos.

Eric Qi Ang
8288 0282
Not Authorised.

Excess : TBA -

12/9/2022

10 Days