

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008965/KPA3Q2**Date:** 21/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900101420
Claimant Vehicle No :	SNB5287E	Insured Vehicle No :	SML5481U
Date of Loss:	10/09/2022	Nature of Claim:	TP
		Claim No:	1058970988SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB5287E	Engine No:	LEB3133155
Make & Model:	HONDA FIT, 1.5 HYBRID (A)	Chassis No:	GP53117119
Reg. Date:	17/06/2015 (Man. Year: 2014)	Odometer:	204039 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	'GREENTRAC' 9 mm	Rear Left Side:	PETLAS 6 mm
Front Right Side:	'GREENTRAC' 9 mm	Rear Right Side:	PETLAS 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,274.72	2,238.19	1,036.53	31.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,350.00	500.00	27.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,124.72	3,588.19	1,536.53	29.98
Approved Total (Overridden) (\$\$)		2,800.00		
(\$\$)	5,124.72	2,800.00	2,324.72	45.36
+ GST 7.00/7.00% (\$\$)	358.73	196.00	162.73	45.36
Nett Amount (\$\$)	5,483.45	2,996.00	2,487.45	45.36
+ Loss of Use (5.0 x S\$60.00/day) (\$\$)		300.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		3,298.00		

INSPECTION

Date of Assignment:	13/09/2022	Optima Werkz Pte Ltd (HQ)
Date Inspected:	13/09/2022 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
		Autopoint
		Singapore 568047
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	952.50 FL	*952.50 FL
2	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	137.30 FL	*137.30 FL
3	1		*REAR TAILGATE OUTER CHROME GARNISH	Serviceable	168.90 FL	*- FL
4	1		*REAR TAILGATE FIT EMBLEM	Necessary	38.80 FL	*38.80 FL
5	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	37.50 FL	*37.50 FL
6	1		*REAR TAILGATE MECHANISM LOCK	Dented	110.80 FL	*110.80 FL
7	1		*REAR TAILGATE INNER HANDLE COVER	Serviceable	32.60 FL	*- FL
8	1		*REAR TAILGATE INNER TRIM BOARD	Mtg Cracked	145.80 FL	*145.80 FL
9	1		*REAR TAILGATE WEATHERSTRIP (50%)	Cut	81.84 FS	*51.15 FS
10	1		*REAR TAIL LAMP LH	Serviceable	374.70 FL	*- FL
11	1		*REAR TAIL LAMP RH	Cracked	374.70 FL	*366.10 FL
12	1		*REAR BUMPER	Buckled	703.10 FL	*521.60 FL
13	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	28.50 FL	*- FL
14	1		*REAR BUMPER SIDE RETAINER RH	Distorted	28.50 FL	*28.50 FL
15	1		*REAR END PANEL TOP GARNISH	Mtg Cracked	102.20 FL	*102.20 FL
16	1		*REAR END PANEL (NPA)	Repair	0.00 FL	*- FL
17	1		*REAR BUMPER INNER BUZZLE	Cracked	92.70 FL	*92.70 FL
18	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
19	1		*REAR NUMBER PLATE WITH HOLDER	Serviceable	50.00 FS	*- FS
20	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	40.00 FS	*40.00 FS
21	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
22	1		*REAR BUMPER REVERSE SENSOR	Serviceable	300.00 FS	*- FS
23	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,940.44	2,744.95
- List Item Discount on L Items 20.00/20.00% (\$)	665.72	506.76
Total Parts (\$)	3,274.72	2,238.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST AT ACCIDENT AREA	New	700.00	500.00
2	LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREA	New	700.00	600.00
3	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS & ETC	New	150.00	120.00
4	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC BACK TO ORIGINAL OPERATIONS	New	120.00	60.00
5	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	100.00	50.00
6	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	20.00
Gross Labour Cost (\$\$)			1,850.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >