

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22008966/UPA3Q2**Date:** 07/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100473112
Claimant Vehicle No :	SLK3818M	Insured Vehicle No :	SLD8896R
Date of Loss:	10/09/2022	Nature of Claim:	TP
		Claim No:	9583263734SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK3818M	Engine No:	10FKA72533837
Make & Model:	PEUGEOT 3008, 1.6 (A)	Chassis No:	VF3M45GFRKS124939
Reg. Date:	28/02/2020 (Man. Year: 2019)	Odometer:	25602 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,939.76	8,927.96	9,011.80	50.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,640.00	2,340.00	1,300.00	35.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,579.76	11,267.96	10,311.80	47.78
Approved Total (Overridden) (S\$)		9,000.00		
Nett Amount (S\$)	21,579.76	9,000.00	12,579.76	58.29
+ Car Rental (10.0 x S\$100.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		10,002.00		

INSPECTION

Date of Assignment:	13/09/2022	Zoom Autowerks Pte Ltd (HQ)
Date Inspected:	13/09/2022 Inspected At:	130 Bedok Reservoir Road, Eunos Spring, #08-1339
Estimated Period of Repair:	9.0 days	Singapore 470130

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	85.00 FL	*- FL
2	1		*REAR TAILGATE	Repair	1,850.00 FL	*- FL
3	1		*REAR TAILGATE INNER LOCK	Not Necessary	245.00 FL	*- FL
4	1		*REAR TAILGATE RUBBER	Not Necessary	146.00 FL	*- FL
5	1		*REAR TAILGATE 3008 EMBLEM	Necessary	85.00 FL	*85.00 FL
6	1		*REAR END PANEL	Repair	865.00 FL	*- FL
7	1		*REAR END PANEL INNER GARNISH	Not Necessary	192.00 FL	*- FL
8	1		*REAR END PANEL AIR VENT	Not Necessary	42.00 FL	*- FL
9	1		*REAR BUMPER	Distorted	1,455.00 FL	*1,065.00 FL
10	2		*REAR BUMPER SIDE	Repair	1,350.00 FL	*- FL
11	2		*REAR BUMPER BRACKETS	Not Necessary	164.00 FL	*- FL
12	1		*REAR BUMPER CHROME MOULDING	Cracked	685.00 FL	*520.00 FL
13	2		*REAR BUMPER REFLECTORS	Not Necessary	236.00 FL	*- FL
14	1		*REAR BUMPER REINFORCEMENT	Bent	685.00 FL	*685.00 FL
15	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	130.00 FL	*- FL
16	1		*REAR BUMPER TOW HOOK COVER	Deformed	28.00 FL	*28.00 FL
17	4		*REAR BUMPER PDC SENSORS	Shorted (1 PCS ONLY)	1,260.00 FL	*195.00 FL
18	1		*REAR FENDER WHEEL ARCH GARNISHES	O/S Torn	760.00 FL	*297.00 FL
19	1		*FRONT HEADLAMP -RH	Cracked	3,675.00 FL	*2,671.00 FL
20	1		*FRONT GRILLE	Cracked	525.00 FL	*525.00 FL
21	1		*FRONT GRILLE CHROME MOULDING	Scratched	462.00 FL	*355.00 FL
22	1		*FRONT GRILLE LOGO	Not Necessary	147.00 FL	*- FL
23	1		*FRONT BUMPER	Distorted	1,785.00 FL	*1,050.00 FL
24	1		*SET FRONT BUMPER SIDE BRACKET	O/S Bent	252.00 FL	*80.00 FL
25	1		*FRONT BUMPER CENTRE GRILLE LOWER	Distorted	396.00 FL	*180.00 FL
26	1		*FRONT BUMPER LOWER	Deformed	315.00 FL	*315.00 FL
27	1		*FRONT BUMPER FOG LAMP COVER (O/S)	Twisted / Cut	135.70 FL	*135.70 FL
28	1		*FRONT BUMPER FOG LAMP CHROME MOULDING	Cracked	100.70 FL	*100.70 FL
29	1		*FRONT BUMPER INNER SPONGE	Torn	285.00 FL	*243.00 FL
30	1		*FRONT BUMPER BEAM	Bent	650.00 FL	*580.00 FL
31	1		*FRONT BUMPER TOW HOOK COVER	Deformed	63.00 FL	*42.00 FL
32	1		*FRONT BUMPER UNDERCOVER	Distorted	315.00 FL	*315.00 FL
33	1		*FRONT SUPPORT PANEL	Cracked	297.00 FL	*297.00 FL
34	1		*FRONT LICENCE PLATE	Bent	80.00 FS	*40.00 FS
35	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*50.00 FS
36	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	19,906.40	9,904.40
- List Item Discount on L Items 10.00/10.00% (\$)	1,966.64	976.44
Total Parts (\$)	17,939.76	8,927.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING }	New	80.00	30.00
2	TO REMOVE ,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING }	New	80.00	0.00
3	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	60.00
4	TO REMOVE AND REFIT REAR REVERSE SENSOR AND FRONT SENSOR	New	200.00	50.00
5	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	80.00	0.00
6	TO APPLY UNDERCOATING	New	150.00	0.00
7	PANEL BEATING	New	1,500.00	1,100.00
8	TO RESPRAY PAINTING ON THE AFFECTED AREAS	New	1,400.00	1,100.00
Gross Labour Cost (\$)			3,640.00	2,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >