



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
 #08-1339 Singapore 470130
 Tel: 9450 7920
 * zoomautowerks@gmail.com

not Arnold
2/11
13/09/22
2/s \$9000
9 days.

14 September 2022

REG NO.: SLK 3818 M
 MAKE/MODEL: PEUGEOT 3008

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION		AMT(\$)	
LIST ITEMS				
1	Rear windscreen inner seal	17	\$	85.00 X
1	Rear tailgate	2	\$	1,850.00 X
1	Rear tailgate inner lock	17	\$	245.00 X
1	Rear tailgate rubber	17	\$	146.00 X
1	Rear tailgate "3008" emblem	2/11	\$	85.00 ✓
1	Rear end panel	2	\$	865.00 X
1	Rear end panel inner garnish	17	\$	192.00 X
1	Rear end panel air vent	17	\$	42.00 X
1	Rear bumper	Dis 1065	\$	1,455.00 ✓
2	Rear bumper side	2	\$	1,350.00 X
2	Rear bumper brackets	17	\$	164.00 X
1	Rear bumper chrome moulding	one 520	\$	685.00 ✓
2	Rear bumper reflectors	17	\$	236.00 X
1	Rear bumper reinforcement	But	\$	685.00 ✓
2	Rear bumper side retainers	17	\$	130.00 X
1	Rear bumper tow hook cover	De	\$	28.00 ✓
4	Rear bumper PDC sensors	Should 195	\$	1,260.00 12C
2	Rear fender wheel arch garnishes	0/5 2011 297	\$	760.00 12C
1	Front headlamp -RH	one 2671	\$	3,675.00 ✓
1	Front grille	one	\$	525.00 ✓
1	Front grille chrome moulding	SCR 355	\$	462.00 ✓
1	Front grille logo	17	\$	147.00 X
1	Front bumper	Dis 1060	\$	1,785.00 ✓
2	Front bumper side brackets (2 set)	0/5 But 80	\$	252.00 12C
1	Front bumper centre grille lower	Dis 180	\$	396.00 ✓
1	Front bumper lower	De	\$	315.00 ✓
1	Front bumper fog lamp cover	Dis 1121/1017	\$	135.70 ✓
1	Front bumper fog lamp chrome moulding	one	\$	100.70 ✓
1	Front bumper inner sponge	Turn 243	\$	285.00 ✓
1	Front bumper beam	But 580	\$	650.00 ✓
1	Front bumper tow hook cover	De 42	\$	63.00 ✓
1	Front bumper undercover	Dis	\$	315.00 ✓
1	Front support panel	one	\$	297.00 ✓
			\$	19,666.40
		Less 10%	\$	1,966.64
			\$	17,699.76

SPECIAL NETT ITEMS

1	front licence plate	\$	Bent	80.00	40
1	Rear bumper clip (1 set)	\$	net	80.00	50
1	Front bumper clip (1 set)	\$	net	80.00	50
		\$		<u>240.00</u>	

S/N LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$		80.00	
2	To remove, replaced damaged lamps and check up rear wiring.	\$		80.00	330
3	To remove and refit inner garnishes.	\$		150.00	60
4	To remove and refit rear reverse sensor and front sensor.	\$		200.00	50
5	To transfer rear tailgate mechanism and wiring assembly.	\$		80.00	X
6	To apply undercoating.	\$	u1	150.00	X
7	Panel beating.	\$		1,500.00	1100
8	To re-spray painting on the affected areas.	\$		1,400.00	1100
		\$		<u>3,640.00</u>	

GRAND TOTAL :

\$ 21,579.76

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1-97644
102
8787-96
140
2340
112679