

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22008971/UNY3E2**Date:** 03/10/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001959634
Claimant Vehicle No :	SML126D	Insured Vehicle No :	SLG6835P
Date of Loss:	09/09/2022	Nature of Claim:	TP
		Claim No:	284680

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML126D		
Make & Model:	BMW X2, 1.5 SDRIVE18I MSPT LED FOG LIGHTS (A)	Engine No:	30685317B38A15A
Reg. Date:	28/09/2018 (Man. Year: 2018)	Chassis No:	WBAYH12070EB36322
Colour:	Gold	Odometer:	69384 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R19	Rear Tyre Size:	225/45 R19
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,566.65	2,171.09	9,395.56	81.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,920.00	1,350.00	2,570.00	65.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,486.65	3,521.09	11,965.56	77.26
Approved Total (Overridden) (S\$)		2,800.00		
Nett Amount (S\$)	15,486.65	2,800.00	12,686.65	81.92

INSPECTION

Date of Assignment:	13/09/2022		
Date Inspected:	13/09/2022	Inspected At:	Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53 Singapore 417808
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Sep 2022)

Parts: M1-SUV BMW X2 1.5 SDRIVE18I MSPT LED FOG LIGHTS (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SML126D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	85.00 FL	*- FL
2	1		*REAR TAILGATE	Repair	1,796.10 FL	*- FL
3	2		*REAR TAILGATE LAMPS	Not Necessary	611.00 FL	*- FL
4	1		*REAR TAILGATE LOCK	Not Necessary	259.80 FL	*- FL
5	1		*REAR TAILGATE RUBBER	Not Necessary	196.10 FL	*- FL
6	1		*REAR TAILGATE X2 EMBLEM	Not Necessary	65.00 FL	*- FL
7	1		*REAR TAILGATE 5 DRIVE EMBLEM	Not Necessary	60.00 FL	*- FL
8	1		*REAR TAILGATE 113I EMBLEM	Not Necessary	65.00 FL	*- FL
9	2		*REAR TAILLAMPS	Not Necessary	871.60 FL	*- FL
10	1		*REAR END PANEL	Repair	920.00 FL	*- FL
11	1		*REAR END PANEL INNER GARNISH	Not Necessary	213.00 FL	*- FL
12	1		*REAR BUMPER	Dented / Deformed	1,698.85 FL	*1,255.62 FL
13	2		*REAR BUMPER REFLECTORS	Not Necessary	124.00 FL	*- FL
14	1		*REAR BUMPER LOWER	Dented / Deformed	801.80 FL	*535.00 FL
15	2		*REAR BUMPER REINFORCEMENT STAYS	Not Necessary	290.00 FL	*- FL
16	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	442.00 FL	*- FL
17	1		*REAR BUMPER PDC SENSORS (4PCS)	Shorted (1Pc Only)	1,484.80 FL	*198.00 FL
18	1		*REAR BUMPER INNER GARNISH	Cracked	245.00 FL	*202.00 FL
19	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	93.90 FL	*- FL
20	2		*REAR NUMBER PLATE LAMPS	Not Necessary	147.80 FL	*- FL
21	1		*REAR FLOOR BOARD	Not Necessary	544.50 FL	*- FL
22	1		*REAR FLOOR PANEL	Not Necessary	614.70 FL	*- FL
23	2		*REAR WHEEL ARCH GARNISHES	Not Necessary	356.00 FL	*- FL
24	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
25	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
26	1		*REAR NUMBER PLATE	Bent	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,165.95	2,280.62
- List Item Discount on L Items 5.00/5.00% (\$\$)	599.30	109.53
Total Parts (\$\$)	11,566.65	2,171.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	80.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	80.00	0.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	0.00
6	TO APPLY UNDERCOATING	New	150.00	0.00
7	PANEL BEATING	New	1,600.00	400.00
8	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	800.00
Gross Labour Cost (\$\$)			3,920.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >