



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMS 8289C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	1,691.00	1,525.00
2	FRONT BUMPER SIDE RETAINER @\$148.00	NOT NECESSARY	296.00	-
1	HEAD LAMP LH	NOT NECESSARY	3,154.00	-
1	FRONT FENDER LH	DENTED	1,102.00	1,102.00
1	FRONT FENDER COWLING LH (FRONT)	NOT NECESSARY	228.00	-
1	FRONT DOOR LH	DENTED	2,584.00	2,210.00
1	FRONT DOOR CHROME MOULDING LH	NOT NECESSARY	227.00	-
1	FRONT DOOR OUTER HANDLE LH	CUT	228.00	228.00
1	FRONT DOOR SIDE MIRROR LH	NOT NECESSARY	1,007.00	-
1	FRONT DOOR SIDE MIRROR HOUSING LH	CUT	275.00	275.00
	LESS 10% DISCOUNT		-1,079.20	-534.00
			9,712.80	4,806.00
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIP (SN)	NOT NECESSARY	120.00	-
1	SET FRONT BUMPER BOTTOM GARNISH CLIP (SN)	NOT NECESSARY	60.00	-
1	SET FRONT FENDER COWLING CLIPS (SN)	NOT NECESSARY	80.00	-
1	FRONT DOOR SEALANT RH (SN)	NOT NECESSARY	150.00	-
1	SET FRONT DOOR INNER TRIM CLIP RH (SN)	NOT NECESSARY	60.00	-
1	FRONT DOOR SIDE MIRROR COVER (SPECIAL TYPE) (SN)	CUT	550.00	280.00
			1,020.00	280.00
<u>LABOUR</u>				
	PANEL BEATING, REMOVING AND REPLACING PARTS.		1,400.00	600.00
	SPRAY PAINTING TO AFFECTED AREAS.		1,400.00	800.00
	WIRING CHECK.		150.00	30.00
	REFOCUS HEADLAMP BEAM.	NOT NECESSARY	60.00	-
	REMOVE AND REFIX FRONT DOOR GLASS.		80.00	40.00
	REMOVE AND REFIX FRONT DOOR MECHANISM.		80.00	40.00
	REMOVE AND REPLACE FRONT BUMPER SENSOR.		120.00	50.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	600.00	-
			3,890.00	1,560.00
GRAND TOTAL			14,622.80	6,646.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,300.00

Report Ref No. CS/UOI22008975/Avy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.