

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|--|-------------------------------|-----------------|---------|-----------------------|--|
| | MS FIRST CAPITA | L INSURANCE LTD | F | Ref: | CS/FCI22008976/Rvy3e2 | |
| | 16 RAFFLES QUA #42-01 HONG LEC SINGAPORE 0485 | NG BUILDING | Г | Date: | 27/04/2023 | |
| | | | (| Code: | FCI2 | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SGY 9894M | Veh. Inspected | | SML 1360L | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | D22002886MFQC | Excess (\$) | | 0.00 | |
| | Assign From | AINI BINTE | Assign Date | | 13/09/2022 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | HYUNDAI AD AVANTE 1.6 GLS (A) | c.c | | 1591 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2019 | |
| | Chassis No. | KMHD841CMKU908987 | Colour | | GREY | |
| | Odometer | 30878 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | FAIR | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 205/55 R16 | KUMHO | | 6 mm | |
| | L/H Front Tyre | 205/55 R16 | KUMHO | | 6 mm | |
| | R/H Rear Tyre | 205/55 R16 | KUMHO | | 6 mm | |
| | L/H Rear Tyre | 205/55 R16 | KUMHO | | 6 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 09/09/2022 | Inspection Date | | 13/09/2022 | |
| | Survey held at | AUTO INSURE PTE LTD | | | | |
| | | 6 MARSILING LANE S739145 | | | | |
| 5a. | Remarks | | | | | |
| | A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | | Estimate Days of Repair | | | | |
| | ESTIMATED NORI | MAL PERIOD FOR REPAIR: | 6 | 6 Worki | ng Days | |