



**Auto Insure Pte. Ltd.**  
6 Marsiling Lane  
Singapore (739145)  
E: claims01@autoinsure.com.sg  
W: www.autoinsure.com.sg  
T: 3157 2626 F: 6368 0081  
**GST No.: 201437380M**

**Page No.1**

**AUTOMOBILE ASSESSMENT REPORT**

Our Ref: **SML1360L (CK)**  
Your Ref: **SGY9894M**

Date: **12-Sep-22**

BY EMAIL ONLY  
(claims01@autoinsure.com.sg)

**ATTENTION: MOTOR CLAIMS DEPT**

Email : motor\_claims@first-insurance.com.sg

**First Capital Insurance Limited**

6 Raffles Quay #21-00  
Singapore 048580

Assessed Vehicle No : **SML1360L**  
Car Make and Model : **HYUNDAI AVANTE**  
Date of Accident : **9-Sep-22**  
Date of Assessment : **12-Sep-22**

We have carried out a physical assessment of SML1360L at our workshop Auto Insure Pte Ltd sustained damages to the REAR portion of the vehicle.


**4. DESCRIPTION OF DAMAGE**

At the time of the inspection observed that this vehicle had sustained damages to the REAR portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : **L/S**  
Adjusted Amount : **\$ 8,502.77**  
Est. Repair Days : **5**



Pursuant to your instruction, we have **NOT AUTHORIZED** repair.  
The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

**Disclaimer**

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.

No liability or responsibility whatsoever shall be held by

**AUTO INSURE PTE. LTD.** For any reliance on this report by any third party.

Our Ref: **SML1360L**Your Ref: **SGY9894M**

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
<b>PARTS REPLACEMENT - LIST ITEMS</b>				
1	1	REAR BUMPER <i>de</i>		\$ 481 ✓ 625.20
2	1	REAR BUMPER CENTER GARNISH <i>cm</i>		\$ 353 ✓ 492.50
3	1	REAR BUMPER REINFORCEMENT <i>cm</i>		\$ 295 ✓ 347.30
4	1	REAR BUMPER FOG LAMP WITH REFELCTOR LH ? <i>X nn</i>		\$ 253.22
5	1	REAR BUMPER FOG LAMP WITH REFELCTOR RH ? <i>X nn</i>		\$ 253.22
6	1	REAR BUMPER SIDE RETAINER LH ? <i>BR</i>		\$ 58.80 ✓
7	1	REAR BUMPER SIDE RETAINER RH ? <i>BR</i>		\$ 58.80 ✓
8	1	REAR TAILGATE <i>st</i>		\$ 1,624.10 ✓
9	1	TAILGATE WEATHERSTRIP <i>nn</i>		\$ 123.30 ✓
10	1	TAIL LAMP LH <i>X nn</i>		\$ 873.20
11	1	TAIL LAMP RH <i>X nn</i>		\$ 873.20
12	1	REAR TAILGATE HINGE LH <i>X nn</i>		\$ 88.50
13	1	REAR TAILGATE HINGE RH <i>X nn</i>		\$ 88.50
14	1	REAR TAILGATE LOCK ? <i>Jammed</i>		\$ 173.20 ✓
15	1	TAILGATE EMBLEM(AVANTE) <i>nn</i>		\$ 45.50 ✓
16	1	TAILGATE EMBLEM(S) <i>nn</i>		\$ 48 - ✓
17	1	TAILGATE LOGO (H) <i>nn</i>		\$ 56 ✓ 237.90
18	1	REAR END PANEL <i>st</i>		\$ 378.50 ✓
19	1	END PANEL INNER TRIM <i>de</i>		\$ 88.20 ✓
SUB TOTAL			\$	6,683.14
LESS 20%			\$	1,336.63
TOTAL AMOUNT			\$	5,346.51

3783.40  
-20%  
3026.72

Our Ref: **SML1360L**Your Ref: **SGY9894M**

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	REAR BUMPER CLIPS <i>nn</i>		\$ 50.00 <i>30</i>
2	1	REAR BUMPER PARKING SENSORS <i>nn</i>		\$ 250.00 <i>200</i>
3	1	END PANEL SEALANT <i>nn</i>		\$ 60.00 <i>40</i>
SUB TOTAL			\$	360.00
TOTAL PARTS COST			\$	5,706.51 <i>270</i>

Our Ref: **SML1360L**Your Ref: **SGY9894M**

S/NO	DESCRIPTION	EST. BY WORKSHOP
<b>LABOUR &amp; PAINTWORK</b>		
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 1,200.00 <i>600</i>
2	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ 100.00 <i>40</i>
3	TO CONDUCT DIGNOSIS FAULT CODE & RESET	\$ 150.00 <i>60</i>
4	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ 600.00 ✓
5	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ 30.00 ✓
6	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)	\$ 50.00 <i>20</i>
7	TO VACUUM, WAXING & CLEAN	\$ 60.00 <i>X</i>

8	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$	50.00	30
	TOTAL BEFORE GST	\$	7,946.51	
	GST 7%	\$	556.26	1380
	TOTAL (PARTS & LABOUR):	\$	8,502.77	

#### Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

4676.72

Our Workshop has agreed to undertake the job at a sum of \$ 8,502.77 for lump sum with the third party insurance.

L/S - 3741.76  
= 4750

Yours Faithfully,

Jason Heng  
Claims Director

Rasul  
Hp 90010068

6 days

4S

13/07/22 @ 1720

Resurvey after repair

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: